

Jet Propulsion LaboratoryCalifornia Institute of Technology

4800 Oak Grove Drive Pasadena, CA 91109-8099

(818) 354-4321



May 10, 2002

Refer to: 930-02-006-ESB:lc

TO: Distribution

FROM: Eugene S. Burke

SUBJECT: Minutes for the Joint Users Resource Allocation Planning Committee Meeting held

April 18, 2001.

NEXT JURAP MEETING:

Thursday, May 16, 2002 JPL Bldg. 303, Room 411 – 1:00 p.m.

Attendees:

R. Bartoo	D. Holmes	B. Mase	J. Valencia
G. Burke	K.Kim	D. Morris	S. Waldherr
B. Compton	N. Lacey	A. O'Dea	B. Yetter
J. Cucchissi	A. Landon	M. Slade	
D. Doody	S. Lineaweaver	M. Ryan	
J. Hall	M. Marina	P. Tay	
A. Haldermann	K. Martinez	B. Toyoshima	

The Joint Users Resource Allocation Planning Committee meets monthly to review the status of Flight Projects, the requirements of other resource users, and to identify future requirements and outstanding conflicts.

Introductory Remarks - G. Burke

Gene chaired the meeting and welcomed the attending mission representatives to the April JURAP.

RARB Action Items - D. Morris

David Morris summarized the Action Items (AI) from the February 2002 Resource Allocation Review Board (RARB) meeting. Nap Lacey worked with Pamela Wolken to close AI No.3. Mike Wert has provided a response to close AI No 5.

Resource Analysis Team – N. Lacey

Testing and training of MADB/TIGRAS is ongoing. Special studies of MEX, LUNAR-A, Messenger and Cassini are in progress. Major Antenna Downtime re-planning and Mid-Range Schedule Development are ongoing. Weeks 23-26 were released to the DSN on March 21, 2002. Week 27 will be released April 01, 2002, and Weeks 39-42 will start negotiations on March 22, 2002.

DSS Downtime Forecast – J. Valencia

There are a number of significant changes to the DSN Major Antenna Downtime schedule. The changes include moving the DSS-14, DSS-54, and DSS-45 NSP task from 2002 into 2003, the rescheduling of the DSS-24 Ka-band encoder task, and deleting the DSS-15 Antenna Controller Replacement from 2003. In addition, downtimes for the DSS-43 regrout work, and DSS-45 HVAC (Heating Ventilation and Air Conditioning) tasks, were added to the 2002 downtime schedule. Other changes that are currently in review are the re-planning of the DSS-46 Servo Drive from Week 17-20 to Week 30-35 in 2003, and rescheduling the DSS-15 NSP from April to January 2003.

JURAP Resource Allocation Review for April-May 2003 – J. Valencia

A special review of the DSN resource allocation for April – May 2003, addressing significant changes to the Network Simplification Project (NSP) implementation schedule was conducted. The special review focus was on resolving contentions caused by the proposed re-planning of DSS-14, DSS-45, and DSS-54 NSP from 2002 into 2003. Issues discussed at the review were proposed changes to the Major DSN Downtime schedule, periods of contention, significant events, RAPSO analysis and recommendations. The review went well and met all objectives. The Projects provided prompt affirmative responses to all of the RAPSO recommendations. Project representatives for Ulysses and SIRTF were unable to attend the meeting, and were given a time extension for their responses and recommendations.

Goldstone Solar System Radar – M. Slade

DSS-14 successfully supported observations of Near-Earth Asteroid 2002 GDS in March, and GSSR conducted radar imaging of Near-Earth Asteroid 2002 FD6 in April 2002. An article describing the probability (1/300) of the first Near-Earth Asteroid colliding with Earth was published in the April 2002 issue of the journal, SCIENCE.

Radio Astronomy / Special Activities – G. Martinez

The DSN continues to meet support requirements. Two Time Earth Motion Precision Observation (TEMPO) activities were supported in March with no reported data loss. Two CAT M&E activities were supported in March, with 98% of data time utilized. In addition, the DSN supported Space Geodesy Program's (SGP) European experiment, with 94% of the data time utilized.

FLIGHT PROJECTS REPORTS

Chandra – K. Gage

The DSS-54 NSP downtime has moved from 2002 to 2003. The Project requests restoration of DSS-54 support in weeks 43 – 47 of 2002. At the February 2001 RARB, this support was negotiated to use DSS-66.

Voyager - J. Hall

Voyager 1 and Voyager 2's operational status is nominal and the DSN support is good. A hardware problem with the DSN's low power transmitter forced the use of the high power transmitter during the March and early April support. Voyager 1's heliocentric distance is 84.4 Astronomical Units (AU), with a round-trip-light-time (RTLT) of approximately 23h 15m. Voyager 2 heliocentric distance is 66.8 AU, with RTLT of approximately 18h 30m.

Cassini – D. Doody

Operations are essentially nominal. Minor spacecraft instrument anomalies and recovery are solved in near real time. On April 3, 2002, the DSN successfully supported Main Engine TCM-18. The Cassini Network Operations Project Engineer (NOPE) was replaced during Cassini's TCM-18. Replacement of key operations support personnel during high-level support activity must be better planned. Cassini Project representatives met with the NOPE, Radio Science, and Telecom engineers to discuss and identify the probable cause of failed Uplink Transfers during GWE-1 DSN support.

MAP, ACE, and IMAGE – S. Waldherr

MAP, ACE and IMAGE spacecraft operations are nominal with no DSN ground support problems reported.

Ulysses – Michelle Medina (for B. Brymer)

Spacecraft operations are nominal. Ulysses is in continuous view from the northern hemisphere and cannot be viewed from the southern hemisphere. Spacecraft reconfigurations and instrument calibrations are performed as required and Earth pointing maneuvers are performed every four days. Three significant Discrepancy Reports were written during this reporting period.

Galileo – Michelle Medina (for B. Compton)

Galileo routine activities include propulsion maintenance activities, and gyro performance tests. Significant events include the completion of final SSI, NIMS calibrations, and encounter I-33 playback that ends remote sensing for the Project. During a routine DMS conditioning, the tape stopped and the DMS fault protection was tripped. Real-time commands were sent to unlock and move the tape. The tape moved, but did not synchronize properly. In addition, high motor current values were seen. The problem continues to be investigated.

Reports not presented this month:

DSN Operations – J. Hodder
Stardust - R. Ryan
Genesis – E. Hirst
ISTP, WIND, POLAR, SOHO, GEOTAIL, Cluster II – A. Chang
Mars Mission Management Office (MMO) - E. Brower

The next JURAP meeting will be held: Thursday, May 16, 2002, at JPL in Bldg. 303, Room 411, at 1:00 p.m.

Note: Teleconference number: (818) 354-2626

2003 – Contention Period - April – Weeks 14 -17

A. DSS-14 has downtime for NSP implementation in Weeks 17 – 20. To accommodate the downtime, GBRA, Galileo, MAP, SOHO, STF, Voyager 1, and Maintenance have all agreed to accept the RAPSO recommendations listed below:

Item No.

Recommendations

- 1. DSS will delete DSS-14 Maintenance support in Week 17.
- 2. GBRA agreed to change the 70m M-Wave Spect support in Week 17 to DSS-43, 63, and reduce to two supports per week. GBRA agreed to delete Planet R/AST in Week 17.
- 3. Galileo agreed to change the 70m routine support in Week 17 to DSS-43, 63.
- 4. MAP agreed to change the 70m routine and Maneuver supports in Week 17 to DSS-43, 63.
- 5. SOHO agreed to change the DSS-14 TSO support in Week 17 to DSS-15 (D/L only).
- 6. Ulysses DSS-14 routine support in Week 17 will move to DSS-15 (D/L only).
- 7. Voyager 1 agreed to change DSS-14, and 63 routine support in Week 17 to DSS-63. Voyager 1 agreed to change the 70m routine uplink support in Week 17 to DSS-43, 63.
- B. DSS-45 has downtime for NSP implementation in Weeks 15 18. To accommodate the downtime, Cassini, Cluster, GBRA, Maintenance, MGS, SGP, Stardust, and STF have all agreed to the RAPSO recommendations listed below:
 - 8. Cassini agreed to change DSS-45, 25 TCM support in Weeks 15 17 to DSS-34, 25. Cassini agreed to change DSS-45 routine support in Week 15 to DSS-25.
 - 9. CLU2 agreed to change DSS-34/45/43 SSO support in Weeks 15 17 to DSS-34/43. CLU2 agreed to change DSS-34/45/43 MSO support in Week 17 to DSS-34/43.
 - 10. DSS-45 will delete Maintenance support in Weeks 15 17.
 - 11. GBRA agreed to move DSS-45 Host Country support in Week 17 to Week 14.

- 12. MGS agreed to change 34H Map/Beta support in Week 17 to DSS-15, 34, 65.
- 13. SGP Crust Dyn agreed to move DSS-45 W-M4 support in Weeks 15 and 16 to Weeks 37 and 38.
- 14. Stardust agreed to change DSS-45, 65 routine support in Weeks 14 17 to DSS-15, 65.
- 15. STF agreed to change DSS-45, 65 routine support in Weeks 15 17 to DSS-15, 65.
- C. DSS-54 has downtime for NSP implementation in Weeks 17 20. To accommodate the downtime, CHDR, Image, STF, M01O Mapping, and Wind have all agreed to accept the RAPSO recommendations as listed below:
 - 16. CHDR agreed to change the 34B1 routine support in Week 17 to DSS-24, 34, 66.
 - 17. DSS-54 agreed to delete Maintenance support in Week 17.
 - 18. Genesis agreed to change the 34B1 routine support in Week 17, to DSS-24, 34.
 - 19. IMAGE agreed to change the 34B1 routine support in Week 17, to DSS-24, 34.
 - 20. Mars Odyssey agreed to change the DSS-25, 34, 54 Mapping support in Week 17, to DSS-25, 34, 65.
 - 21. WIND agreed to change the 34B1 routine support in Week 17, to DSS-24, 34.
 - 22. STF agreed to change DSS-25, 34, 54 routine support in Week 17, to DSS-25, 34, 63.

2003 – Contention Period - May – Weeks 18 –22

A. DSS-14 has downtime for NSP implementation in Weeks 17 – 20. To accommodate the downtime, Galileo, Maintenance, GBRA, GPB, GSSR, MAP, MEGA, and Voyager 1 have all agreed to accept the RAPSO recommendations as listed below:

Item No.

Recommendations

- 1. DSN will change 70m Antenna Cals in Week 18 and 19 to DSS-43, 63.
- 2. DSS-14 will delete routine and bearing Maintenance supports in Weeks 18 and 19, and will delete one routine maintenance in Week 20 (Monday).
- 3. GBRA agreed to change the 70m M-Wave Spect support in Week 18 and 19 to DSS-43, 63 and to reduce support to two per week. GBRA agreed to delete Planet R/AST support in Week 18 and 14. GBRA agreed to move DSS-14/63 SOC-M4 support in Week 19 to Week 20.
- 4. Galileo agreed to change the 70m routine support in Weeks 18 and 19 to DSS-43, 63.
- 5. Gravity Probe B agreed to move DSS-14, 12-hour support; DSS-63, 8-hour support; and DSS-43, 6.5 hour support in Week 19 to Week 20.
- 6. GSSR agreed to delete DSS-14/15 GODR support in Week 19.
- 7. MAP agreed to change the routine 70m support in Weeks 18 and 19 to DSS-43, 63.
- 8. MEGA agreed to change the 70m routine support in Week 19 to DSS-43, 63.
- 9. Ulysses DSS-14 routine support in Week 18 and 19 move to DSS-15 D/L only.
- 10. Voyager 1 agreed to change the 70m routine uplink support in Weeks 18 and 19 to DSS-43, 63. Voyager 1 agreed to change DSS-14 ASCAL support in Week 19 to DSS-15. Voyager 1 agreed to delete the DSS14/15, 14/26 DTR Array support in Week 18. Voyager 1 agreed to change the DSS-14 MAGROL support in Week 19 to DSS-15.
- B. DSS-45 has downtime for NSP implementation in Weeks 17–20. To accommodate the downtime, Cassini, Maintenance, Cluster, MGS, and Stardust, have all agreed to accept the RAPSO recommendations listed below:

- 11. Cassini agreed to change DSS-45, 25 TCM support in Week 18 to DSS-34, 25. Cassini agreed to change DSS-45, 65, 25 TCM Day support in Week 18 to DSS-34, 65, 25.
- 12. CLU2 agreed to change DSS-34/43/45 SSO support in Week 18 to DSS-34/43.
- 13. DSS-45 agreed to delete Maintenance support in Week 18.
- 14. MGS agreed to change the 34H Map/Beta support in Week 18 to DSS-15, 34, 65.
- 15. Stardust agreed to change DSS-45, 65 routine support in Week 18 to DSS-15, 65.
- 16. STF agreed to change routine support at DSS-45, 65 in Week 18 to DSS-15, 65.
- C. DSS-54 has downtime for NSP implementation in Weeks 17 20. To accommodate the downtime, CHDR, Maintenance, Genesis, Image, Nozomi, M010 Mapping, Polar, and WIND have agreed to accept the RAPSO recommendations listed below:
 - 17. CHDR agreed to change the 34B1 routine support in Weeks 18 and 19 to DSS-24, 34, 66.
 - 18. DSS-54 agreed to delete Maintenance support in Weeks 18 and 19.
 - 19. Genesis agreed to change 34B1 routine support in Weeks 18 and 19 to DSS-24, 34.
 - 20. IMAGE agreed to change the 34B1 routine support in Weeks 18 and 19 to DSS-24, 34.
 - 21. Nozomi agreed to change DSS-24, 54 routine support in Weeks 18 and 19 to DSS-24.
 - 22. Mars Odyssey agreed to change at DSS-25, 34, 54 Mapping support in Weeks 18 and 19 to DSS-24, 34, 65.
 - 23. Polar agreed to change 34B1 PB support in Week 19 to DSS-24, 66.
 - 24. Ulysses DSS-54 routine support in Weeks 18 and 19 change to DSS-65 D/L only.
 - 25. WIND agreed to change the 34B1 routine support in Weeks 18 and 19 to DSS-24, 34.
 - 26. STF agreed to change DSS-25, 34, 54 routine support in Weeks 18 and 19 to DSS-25, 34, 63.

ACE Afkhami, F. GSFC m/s 428.2 Sodano, R. J. GSFC m/s 581.0	Goldstone Orbital Debris Radar (GODR)Goldstein, R. M. (PM)300-227Wolken, P. R.507-105
Canberra Deep Space Communications Complex Churchill, P	Goldstone Solar System Radar (GSSR) Haldemann, A. F
Jacobsen, R. CDSCC O'Brien, J. J. CDSCC	Hills, D. L. 238-420 Ostro, S. J. (PS) 300-233
Ricardo, L. CDSCC Robinson, A. CDSCC Wiley, B. CDSCC	Slade, III, M. A. (PM) 238-420 Wolken, P. R. 507-105
Cassini	Gravity Probe-B 264-235
Arroyo, B. 264-235 Chin, G. E. 230-310 Doody, D. F. 230-310	Keiser, M. (PS)
Frautnick, J. C. 230-301 Gustavson, R. P. 230-301	IMAGE Abramo, C. A
Maize, E. H. 230-104 Mitchell, R. T. (PM) 230-205 Webster, J. L. 230-104	Burley, R. J. GSFC m/s 632.0 Green, J. L. GSFC m/s 630
Chandra	IPN-ISD / General Doms, P. E
Bucher, S. SAO Gage, K. R. SAO Lavoie, A. R. (PM) MSFC Org. FD03	Polansky, R. G. 303-400 Stelzried, C. T. 303-407 Weber, III, W.J. 303-400
Marsh, K	IPN-ISD / DSMS Engineering
Wicker, D. SAO Wright, G. M. MSFC Org. FD03	Freiley, A. J
Dawn Arroyo, B	Klose, J. C. 303-404 Kurtik, S. C. 303-210 Osman, J. W. 303-210
Gavit, S. A. (PM)	Sible, Jr., R. W. 303-404 Statman, J. I. 303-404
Europa Arroyo, B	IPN-ISD / DSMS Operations
McNamee, J.B. (PM) 301-335 Simpson, K.A. 301-335	Almassy, W. T. 502-420 Berman, A. L. 303-403 Covate, J. T. 507-120
Galileo	Dillard, D. E
Compton, B	Frazier, R
Medina-Gussie, M. 301-371 Pojman, J. L. 238-538 Trivilla F. F. (2006) 264-536	Green, J. C. 507-120 Hodder, J. A. 303-403
Theilig, E. E. (PM)	Knight, A. G. 507-120 Martinez, G. 507-120 Nevarez, R. E. 502-400
Arroyo, B	Recce, D. J. 303-403 Roberts, J. P. 502-400
Hirst, E. A	Salazar, A. J. 303-403 Schroeder, H. B. 507-120
Sweetnam, D. N. 264-370 Tay, P. 264-235	Short, A. B. 507-120 Wackley, J. A. 303-403
Yetter, K. E	Watzig, G. A. 502-420 Wert, M. 502-420
Goldstone Deep Space Communications ComplexHolmgren, E.DSCC-25Massey, K.DSCC-61McCoy, J.DSCC-57Millmore, D.DSCC-37	302-420

IDNI ICD DCMC Dlang & Commitments	IDI /Caranal
IPN-ISD DSMS Plans & Commitments Abraham, D. S	JPL/General Burgess, L. N. 230-107
Altunin, V. I	Burton, M. E
Bathker, D. A	Finley, S. G
Benson, R. D	Gershman, R
Beyer, P. E	Holladay, J. A
Black, C. A	Jurgens, R. F
Cesarone, R. J. 303-402	Kahn, P. B
Chang, A. F	Kliore, A. J
Gillette, R. L	Kobrick, M
Holmes, D. P	Moore, W. V
Kwok, A	Morabito, D. D
Miller, R. B	Naudet, C. J
Moyd, K	Robbins, P. E
Peng, T. K	Silva, A
Poon, P. T	Smith, J. L
Slusser, R. A	Taylor, A. H
Waldherr, S	Toyoshima, B
Yetter, B. G	Winterhalter, D
,	Woo, H. W
IPN-ISD / DSMS RAPSO	Yung, C. S
Bartoo, R. H	
Borden, C. S	Madrid Deep Space Communications Complex
Burke, E. S	Gimeno, J MDSCC
Hampton, E	Gonzalez, C MDSCC
Kehrbaum, J. M	Martin, A MDSCC
Kim, K	Rosich, A MDSCC
Lacey, N	354 D
Lineaweaver, S	MAP
Martinez, K. A	Abramo, C. A
Morris, D. G	Coyle, S. E
Valencia, J. 504-102 Wang, Y-F. 301-165	Dew, H. C. GSFC m/s 423.0 Mahmot, R. E. (PM) GSFC m/s 444.0
Zendejas, S. C	Mailinot, R. E. (FM)
Zenacjas, 5. C	Mars Exploration Rover (MER A & B)
ISTP (Cluster II)	Adler, M
Abramo, C. A	Arroyo, B
Christensen, J. L GSFC m/s 404.0	Crisp, J. A. (PS)
Dutilly, R. N GSFC m/s 581.1	Erickson, J. K
Gurnett, D U. of Iowa	Ludwinski, J.M
Mahmot, R. E. (PM) GSFC m/s 444.0	Roncoli, R. B
Pickett, J U. of Iowa	Theisinger, P. C. (PM)
ISTP (GEOTAIL/POLAR/SOHO/WIND)	Mars Express Orbiter
Abramo, C. A	Arroyo, B
Alexander, H	Horttor, R. L. (PM)
Bush, R. I Stanford Univ.	Thompson, T. W
Carder, M. E	Many Clabal Summer
Dutilly, R. N. GSFC m/s 581.1 Giles, B. L. GSFC m/s 692.0	Mars Global Surveyor Albee, A. (PS)
Hearn, S. P	Arroyo, B
Mahmot, R. E	Brower, E. E
Machado, M. J	Thorpe, T. E. (PM)
Milasuk-Ross, J	Yetter, K. E
Miller, K. A. GSFC m/s 450.C	10001, 12. 21
Nace, E. M	Mars Program Office
Odendahl, S. K	Cutts, J. A
·	Jordan, Jr., J. F
	McCleese, D. J
	Naderi, F. M
	Whataal C 264 426

Mars Reconnaissance Orbiter Project Arroyo, B. 264-235 Graf, J. E. (PM) 264-440 Johnston, M. D. 301-140L Lock, R. E. 301-140L
Mars 2001 Odyssey MissionArroyo, B.264-235Gibbs, R.G.264-255Harris, J. A.301-455Landano, M. R. (PM)264-725Mase, R. A.264-380Saunders, R. S. (PS)180-701Spencer, D. A.264-255
Muses-C Arroyo, B. 264-235 Mottinger, N. A. 301-125J Smith, J.G (PM) 264-828
NASA Headquarters Costrell, J. A. Code MT Geldzahler, B. Code SR Hertz, P. Code SR Holmes, C. P. Code SR Spearing, R. E. Code M-3
NASA/ARC/General Campo, R. A. ARC 244-14
NASA/GSFC/General Barbehenn, G. M. GSFC m/s 440.8 Levine, A. J. GSFC m/s 452.0 Martin, J. B. GSFC m/s 451.0
NASA/SOMO Dalton, J. T. GSFC m/s 720.0 Dowen, A. Z. 303-400 Hall, V. F. JSC Code TG Morse, G. A. JSC Code TA Thompson, E. W. JSC Code GA
NOZOMI (Planet B) Arroyo, B. 264-235 Ryne, M. S. 301-276 Tay, P. 264-235 Yetter, K. E. 264-235
PFPD / Mission Management Office Morris, R. B. 264-235 Varghese, P. 264-235
Radio Astronomy Klein, M. J. (PM) 303-402 Kuiper, T. B. (PS) 169-506 Martinez, G. 507-120 Wolken, P. R. 507-105
Reference Frame CalibrationAltunin, V. I.303-402Cangahuala, A. (PM)301-125JJacobs, C.238-600

Space Infrared Telescope Facility (SIRTF)	
Arroyo, B	264-235
Gallagher, D. B. (PM)	264-767
Kwok, J. H	264-767
Stardust	
Arroyo, B.	
Duxbury, T. C. (PM)	264-379
Hirst, E	264-570
Ryan, R. E	301-285
Tay, P	264-235
Yetter, K. E	264-235
Ulysses / Voyager	
Arroyo, B	
Brymer, B. F.	
Cummings, A. C	
Hall, Jr., J. C.	264-801
Massey, E. B. (PM)	264-801
Medina-Gussie, M.	301-225
Nash, J. C	264-114
Smith, E. J. (PS - ULS)	169-506
Stone, E.C. (PS - VGR)	T 220-47
Yetter, K. E.	
U.S. Space VLBI	
Altunin, V. I.	
Miller, K. J.	264-828
Preston, R.A. (PS)	238-332
Smith, J. G. (PM)	264-828
Other Organizations	
Crimi, G. F.	SAIC
Laemmel, G DI	R-GSOC
Wanke, H DI	R-GSOC

Please mark any additions, deletions, or corrections to this distribution list and return to:

David G. Morris Jet Propulsion Laboratory 4800 Oak Grove Drive, 303-403 Pasadena, CA 91109 / 818-393-3535 email: David.G.Morris@jpl.nasa.gov






Joint Users Resource Allocation Planning Committee (JURAP)




Resource Allocation Review April-May 2003

Jose Valencia

April 18, 2002







JURAP Resource Allocation Review

Agenda

- Loading Study
 - Periods of Contention
 - Proposed Major DSN Downtime Changes
 - Events, Analysis and Recommendations



JURAP Resource Allocation Review

Periods of Contention

Month	Weeks
	2003
April	14 - 17
May	18 - 22



JURAP Resource Allocation Review Loading Study


Major DSN Downtimes and Proposed NSP Changes in 2003

- **◆ DSS-14 NSP Implementation**
 - Was planned for 08/15/02 09/27/02 (Weeks 33- 39 / DOY 227- 270)
 - Proposed for 04/21/03 05/12/03 (Weeks 17- 20 / DOY 111- 132)
- DSS-45 NSP Implementation
 - Was planned for 10/01/02 11/22/02 (Weeks 40- 47 / DOY 274- 326)
 - Proposed for 04/07/03 05/02/03 (Weeks 15- 18 / DOY 097- 122)
- **◆** DSS-54 NSP Implementation
 - Was planned for 10/01/02 11/22/02 (Weeks 40 47 / DOY 274- 326)
 - Proposed for 04/21/03 05/12/03 (Weeks 17 20 / DOY 111- 132)



JURAP Resource Allocation Review Loading Study

Major DSN Downtimes and Proposed NSP Changes



Proposed Times

DSS-14 04/21/03 (Mon) - 05/12/03 (Mon) NSP DSS-15 03/03/03 (Mon) - 04/02/03 (Wed) NSP DSS-45 04/07/03 (Mon) - 05/02/03 (Fri) NSP DSS-54 04/21/03 (Mon) - 05/12/03 (Mon) NSP




JURAP Resource Allocation Review Analysis and Recommendations

Events, Analysis and Recommendations



JURAP Resource Allocation Review 2003 Weekly Average User Unsupportable Time





JURAP Resource Allocation Review Analysis and Recommendations

2003 - April (Weeks 14 - 17)

EVENTS

DSS-14 Downtime (NSP) in Weeks 17-20 Proposal

DSS-25 Downtime (NSP) in Weeks 07-14


DSS-34 Downtime (NSP) in Weeks 07-14

DSS-45 Downtime (NSP) in Weeks 15-18 Proposal

DSS-46 Downtime (Servo Drive) in Weeks 15-17

DSS-54 Downtime (NSP) in Weeks 17-20 Proposal

DSS-63 Downtime (Servo Drive) in Weeks 14-16



Cassini TCM support in Weeks 15-17

Genesis Maneuver continuous on the 34B1 in Week 16 on DOY 106-107

Mars Odyssey Mapping support 2 passes per day

MGS Mapping/Beta support 9 to 10 passes per Week

Rosetta Post Launch support in Week 14 at DSS-54 and NAV

Campaign in Weeks 15-16

SIRTF Post Launch and IOC continuous in Week 14 plus 3 days in Week 15



ANALYSIS

- 1. DSS-14 will be down for NSP from Week 17 (Monday DOY 111) through Week 20 (Monday DOY 132) affecting: Galileo, GBRA, Maintenance, MAP, SOHO TSO, Ulysses, and Voyager 1
- 2. DSS-15 Downtime for Antenna Controller Replacement (ACR) in Weeks 10-18 is deleted and is in re-planning for 2004. DSS-15 NSP Downtime in Weeks 14-18 is re-planned for Weeks 10-14 (Monday DOY 062 through Wednesday DOY 092). DSS-15 ACR downtime in Week 14 (Thursday DOY 093) to Week 18 (Thursday DOY 124) will be returned to Projects/Users.
- DSS-45 will be down for NSP re-plan from Week 15 (Monday DOY 097) through Week 18 (Friday DOY 122) affecting: Cassini, Cluster, GBRA, Maintenance, MGS Mapping, Stardust and STF
- 4. DSS-54 will be down for NSP re-plan from Week 17 (Monday DOY 111) through Week 20 (Monday DOY 132) affecting: CHDR, Genesis, Image, Maintenance, M01O, STF, and Wind



RECOMMENDATIONS

DSS-14

- DSS Maintenance delete support in Week 17
- ♦ GBRA M-Wave Spect at 70M in Week 17 change to DSS-43, 63 and reduce to 2 per week
- ◆ GBRA delete Planet R/AST in Week 17
- ◆ Galileo routine support at 70M in Week 17 change to DSS-43, 63
- ◆ MAP routine support at 70M in Week 17 change to DSS-43, 63*
- MAP Maneuver support at 70M in Week 17 change to DSS-43, 63*
- ◆ SOHO TSO support in Week 17 change to DSS-15 (D/L only)*
- ◆ Ulysses routine support at DSS-14 in Week 17 move to DSS-15 (D/L only)
- ♦ Voyager 1 routine support at DSS-14, 63 in Week 17 change to DSS-63*
- ♦ Voyager 1 routine uplink support at 70M in Week 17 change to DSS-43, 63*

* Recommendation accepted



RECOMMENDATIONS

DSS-45

- ◆ Cassini TCM support at DSS-45, 25 in Weeks 15 17 change to DSS-34, 25*
- ◆ Cassini routine support at DSS-45 in Weeks 15 change to DSS-25*
- ◆ CLU2 SSO support at DSS-34/45/43 in Weeks 15 17 change to DSS-34/43*
- ◆ CLU2 MSO support at DSS-34/45/43 in Week 17 change to DSS-34/43*
- ◆ DSS Maintenance delete support in Weeks 15 17
- ◆ GBRA Host Country support in Week 17 move to Week 14
- ◆ MGS Map/Beta support at 34H in Week 17 change to DSS-15, 34, 65*
- ◆ SGP Crust Dyn W-M4 support at DSS-45 in Weeks 15 and 16 move to Weeks 37 and 38
- ◆ Stardust routine support at DSS-45, 65 in Weeks 14 17 change to DSS-15, 65*
- ◆ STF routine support at DSS-45, 65 in Weeks 15 17 change to DSS-15, 65

* Recommendation accepted



JURAP Resource Allocation Review <u>Analysis and Recommendations</u>

2003 – April (Weeks 14 – 17) (continued)

RECOMMENDATIONS

DSS-54

- ◆ CHDR routine support at 34B1 in Week 17 change to DSS-24, 34, 66
- ◆ DSS Maintenance delete support in Week 17
- ◆ Genesis routine support at 34B1in Week 17 change to DSS-24, 34*
- ◆ IMAGE routine support at 34B1 in Week 17 change to DSS-24, 34*
- Mars Odyssey Mapping support at DSS-25, 34, 54 in Week 17 change to DSS-25, 34, 65*
- ♦ Ulysses routine support at DSS-54, 65 in Week 17 change to DSS-63, 65
- ♦ WIND routine support at 34B1 in Week 17 change to DSS-24, 34*
- ◆ STF routine support at DSS-25, 34, 54 in Week 17 change to DSS-25, 34, 63

*Recommendation accepted



User Resource Ave Min Pre Post 14 15 16 17 CAS DSS-45 8.0 4.0 1.00 0.25 2 1 CAS TCM DSS-45,25 9.0 4.0 1.00 0.25 2 3 CHDR 34B1 1.0 1.0 1.00 0.25 21 21 CHDR DSS-24,54 1.0 1.0 1.00 0.25 14 CHDR DSS-46 2.0 2.0 0.70 0.20 7 CLU2 1/2/3/4 SSO DSS-34/45/43 2.0 1.0 0.50 0.25 1 CLU2 1/2/3/4 SSO DSS-16/27/24/14 2.0 1.0 0.50 0.25 1 1 CLU2 1/2/3/4 SSO DSS-46/45/43 2.0 1.0 0.50 0.25 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 </th <th></th> <th>i</th> <th>B ::</th> <th></th> <th>0 111</th> <th>e I</th> <th></th> <th>A "</th> <th></th> <th></th>		i	B ::		0 111	e I		A "		
CAS DSS-45 8.0 4.0 1.00 0.25 2 1 CAS TCM DSS-45,25 9.0 4.0 1.00 0.25 2 3 CHDR 34B1 1.0 1.0 1.00 0.25 21 21 CHDR DSS-24,54 1.0 1.0 1.00 0.25 14 CHDR DSS-46 2.0 2.0 0.70 0.20 7 CLU2 1/2/3/4 SSO DSS-34/45/43 2.0 1.0 0.50 0.25 1 CLU2 1/2/3/4 SSO DSS-34/45/43 2.0 1.0 0.50 0.25 1 1 CLU2 1/2/3/4 SSO DSS-16/27/24/14 2.0 1.0 0.50 0.25 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		_							40	4-
CAS TCM DSS-45,25 9.0 4.0 1.00 0.25 2 3 CHDR 34B1 1.0 1.0 1.00 0.25 21 21 CHDR DSS-24,54 1.0 1.0 1.00 0.25 14 CHDR DSS-46 2.0 2.0 0.70 0.20 7 CLU2 1/2/3/4 SSO DSS-34/45/43 2.0 1.0 0.50 0.25 1 CLU2 1/2/3/4 SSO DSS-34/45/43 2.0 1.0 0.50 0.25 1 CLU2 1/2/3/4 SSO DSS-16/27/24/14 2.0 1.0 0.50 0.25 2 2 2 CLU4 1/2/3/4 SSO DSS-46/45/43 2.0 1.0 0.50 0.25 1 1 CLU4 1/2/3/4 MSO DSS-34/45/43 1.5 1.0 0.50 0.25 1 DSN Antenna Cal DSS-34/45/43 1.5 1.0 0.50 0.25 1 1 1 1 1 1 1 1									16	17
CHDR 34B1 1.0 1.0 1.00 0.25 21 21 CHDR DSS-24,54 1.0 1.0 1.00 0.25 14 CHDR DSS-46 2.0 2.0 0.70 0.20 7 CLU2 1/2/3/4 SSO DSS-34/45/43 2.0 1.0 0.50 0.25 1 CLU2 1/2/3/4 SSO DSS-34/45/43 2.0 1.0 0.50 0.25 2 2 2 CLU2 1/2/3/4 SSO DSS-16/27/24/14 2.0 1.0 0.50 0.25 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2							2	•		
CHDR DSS-24,54 1.0 1.0 1.00 0.25 14 CHDR DSS-46 2.0 2.0 0.70 0.20 7 CLU2 1/2/3/4 SSO DSS-34/45/43 2.0 1.0 0.50 0.25 1 CLU2 1/2/3/4 SSO DSS-34/45/43 2.0 1.0 0.50 0.25 2 2 2 2 CLU2 1/2/3/4 SSO DSS-16/27/24/14 2.0 1.0 0.50 0.25 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		·								4
CHDR DSS-46 2.0 2.0 0.70 0.20 7 CLU2 1/2/3/4 SSO DSS-34/45/43 2.0 1.0 0.50 0.25 1 CLU2 1/2/3/4 SSO DSS-34/45/43 2.0 1.0 0.50 0.25 2 2 2 CLU2 1/2/3/4 SSO DSS-16/27/24/14 2.0 1.0 0.50 0.25 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2								21	21	21
CLU2 1/2/3/4 SSO DSS-34/45/43 2.0 1.0 0.50 0.25 1 CLU2 1/2/3/4 SSO DSS-34/45/43 2.0 1.0 0.50 0.25 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		· ·								
CLU2 1/2/3/4 SSO DSS-34/45/43 2.0 1.0 0.50 0.25 1 CLU2 1/2/3/4 SSO DSS-16/27/24/14 2.0 1.0 0.50 0.25 2 2 2 CLU2 1/2/3/4 SSO DSS-46/45/43 2.0 1.0 0.50 0.25 1 CLU4 1/2/3/4 MSO DSS-34/45/43 1.5 1.0 0.50 0.25 DSN Antenna Cal DSS-14,43 8.0 8.0 1 1 1 DSN Clock Syn D-M4 DSS-65 4.0 4.0 1.50 0.50 1 1 1 DSS Bearing Mntc DSS-14 8.0 8.0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		DSS-46	2.0	2.0	0.70	0.20	7			
CLU2 1/2/3/4 SSO DSS-16/27/24/14 2.0 1.0 0.50 0.25 2 2 2 CLU2 1/2/3/4 SSO DSS-46/45/43 2.0 1.0 0.50 0.25 1 CLU4 1/2/3/4 MSO DSS-34/45/43 1.5 1.0 0.50 0.25 DSN Antenna Cal DSS-14,43 8.0 8.0 1 1 1 DSN Clock Syn D-M4 DSS-65 4.0 4.0 1.50 0.50 1 1 DSS Bearing Mntc DSS-14 8.0 8.0 1 1 1 DSS Bearing Mntc DSS-43 8.0 8.0 1 1 1 DSS Bearing Mntc DSS-63 8.0 8.0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	CLU2 1/2/3/4 SSO	DSS-34/45/43	2.0	1.0	0.50	0.25		1		1
CLU2 1/2/3/4 SSO DSS-46/45/43 2.0 1.0 0.50 0.25 1 CLU4 1/2/3/4 MSO DSS-34/45/43 1.5 1.0 0.50 0.25 DSN Antenna Cal DSS-14,43 8.0 8.0 1 1 1 DSN Clock Syn D-M4 DSS-65 4.0 4.0 1.50 0.50 1 1 DSS Bearing Mntc DSS-14 8.0 8.0 1 1 1 DSS Bearing Mntc DSS-43 8.0 8.0 1 1 1 1 DSS Bearing Mntc DSS-63 8.0 8.0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 <	CLU2 1/2/3/4 SSO	DSS-34/45/43	2.0	1.0	0.50	0.25			1	
CLU4 1/2/3/4 MSO DSS-34/45/43 1.5 1.0 0.50 0.25 DSN Antenna Cal DSS-14,43 8.0 8.0 1 1 1 DSN Clock Syn D-M4 DSS-65 4.0 4.0 1.50 0.50 1 1 DSS Bearing Mntc DSS-14 8.0 8.0 1 1 DSS Bearing Mntc DSS-43 8.0 8.0 1 1 DSS Bearing Mntc DSS-63 8.0 8.0 1 1 1 DSS Maintenance DSS-54 6.0 6.0 1 1 1 1 DSS Maintenance DSS-25 8.0 6.0 1 1 1 1 DSS Maintenance DSS-27 8.0 6.0 1 1 1 1 DSS Maintenance DSS-45 6.0 6.0 1 1 1 1	CLU2 1/2/3/4 SSO	DSS-16/27/24/14	2.0	1.0	0.50	0.25	2	2	2	2
DSN Antenna Cal DSS-14,43 8.0 8.0 1 1 1 1 DSN Clock Syn D-M4 DSS-65 4.0 4.0 1.50 0.50 1 1 DSS Bearing Mntc DSS-14 8.0 8.0 1 1 DSS Bearing Mntc DSS-43 8.0 8.0 1 1 DSS Bearing Mntc DSS-63 8.0 8.0 1 1 1 DSS Maintenance DSS-54 6.0 6.0 1 1 1 1 DSS Maintenance DSS-25 8.0 6.0 1 1 1 1 DSS Maintenance DSS-27 8.0 6.0 1 1 1 1 DSS Maintenance DSS-45 6.0 6.0 1 1 1 1	CLU2 1/2/3/4 SSO	DSS-46/45/43	2.0	1.0	0.50	0.25	1			
DSN Clock Syn D-M4 DSS-65 4.0 4.0 1.50 0.50 1 1 DSS Bearing Mntc DSS-14 8.0 8.0 1 DSS Bearing Mntc DSS-43 8.0 8.0 1 DSS Bearing Mntc DSS-63 8.0 8.0 1 DSS Maintenance DSS-54 6.0 6.0 1 1 1 DSS Maintenance DSS-25 8.0 6.0 1 1 1 DSS Maintenance DSS-27 8.0 6.0 1 1 1 DSS Maintenance DSS-45 6.0 6.0 1 1 1	CLU4 1/2/3/4 MSO	DSS-34/45/43	1.5	1.0	0.50	0.25				1
DSS Bearing Mntc DSS-14 8.0 8.0 1 DSS Bearing Mntc DSS-43 8.0 8.0 1 DSS Bearing Mntc DSS-63 8.0 8.0 DSS Maintenance DSS-54 6.0 6.0 1 1 1 DSS Maintenance DSS-25 8.0 6.0 1 1 1 DSS Maintenance DSS-27 8.0 6.0 1 1 1 DSS Maintenance DSS-45 6.0 6.0 1 1 1	DSN Antenna Cal	DSS-14,43	8.0	8.0			1	1	1	
DSS Bearing Mntc DSS-43 8.0 8.0 1 DSS Bearing Mntc DSS-63 8.0 8.0 DSS Maintenance DSS-54 6.0 6.0 1 1 1 DSS Maintenance DSS-25 8.0 6.0 1 1 1 DSS Maintenance DSS-27 8.0 6.0 1 1 1 DSS Maintenance DSS-45 6.0 6.0 1 1 1	DSN Clock Syn D-M4	DSS-65	4.0	4.0	1.50	0.50	1		1	
DSS Bearing Mntc DSS-63 8.0 8.0 DSS Maintenance DSS-54 6.0 6.0 1 1 1 DSS Maintenance DSS-25 8.0 6.0 1 1 1 DSS Maintenance DSS-27 8.0 6.0 1 1 1 1 DSS Maintenance DSS-45 6.0 6.0 1 1 1 1	DSS Bearing Mntc	DSS-14	8.0	8.0				1		
DSS Maintenance DSS-54 6.0 6.0 1 1 1 1 DSS Maintenance DSS-25 8.0 6.0 1 1 1 DSS Maintenance DSS-27 8.0 6.0 1 1 1 1 DSS Maintenance DSS-45 6.0 6.0 1 1 1 1	DSS Bearing Mntc	DSS-43	8.0	8.0					1	
DSS Maintenance DSS-25 8.0 6.0 1 1 1 DSS Maintenance DSS-27 8.0 6.0 1 1 1 1 DSS Maintenance DSS-45 6.0 6.0 1 1 1 1	DSS Bearing Mntc	DSS-63	8.0	8.0						1
DSS Maintenance DSS-27 8.0 6.0 1 1 1 1 DSS Maintenance DSS-45 6.0 6.0 1 1 1 1	DSS Maintenance	DSS-54	6.0	6.0			1	1	1	1
DSS Maintenance DSS-45 6.0 6.0 1 1 1 1	DSS Maintenance	DSS-25	8.0	6.0				1	1	1
	DSS Maintenance	DSS-27	8.0	6.0			1	1	1	1
DSS Maintenance DSS-24 8.0 6.0 1 1 1	DSS Maintenance	DSS-45	6.0	6.0			1	1	1	1
	DSS Maintenance	DSS-24	8.0	6.0			1	1	1	1
DSS Maintenance DSS-65 6.0 6.0 1 1 1	DSS Maintenance	DSS-65	6.0	6.0			1	1	1	1
DSS Maintenance DSS-26 8.0 6.0 1 1 1	DSS Maintenance	DSS-26	8.0	6.0			1	1	1	1
DSS Maintenance DSS-46 6.0 6.0 1	DSS Maintenance	DSS-46		6.0			1			
DSS Maintenance DSS-66 8.0 6.0 1 1 1	DSS Maintenance		8.0	6.0			1	1	1	
DSS Maintenance DSS-66 4.0 4.0	DSS Maintenance	DSS-66	4.0	4.0						1
DSS Maintenance DSS-43 8.0 8.0 1 1	DSS Maintenance		8.0	8.0			1	1		1
DSS Maintenance DSS-16 8.0 6.0 1 1 1	DSS Maintenance		8.0	6.0			1	1	1	
DSS Maintenance DSS-16 4.0 4.0										1



		Duratio	ons	Calibra	tion		April		
User	Resource	Ave	Min	Pre	Post	14	15	16	17
DSS Maintenance	DSS-34	6.0	6.0			1	1	1	1
DSS Maintenance	DSS-63	6.0	4.0						1
DSS Maintenance	DSS-14	8.0	8.0			1	1	1	2
GBRA Host Country	DSS-45	12.0	12.0	0.75	0.25				1
GBRA M-Wave Spect	70M	9.0	4.0	0.50	0.50				3
GBRA M-Wave Spect	DSS-14,43	9.0	4.0	0.50	0.50	2	2	2	
GBRA Planet R/Ast	DSS-14	9.0	4.0	0.75	0.50	1	1	1	1
GLLO	70M	8.0	4.0	1.00	0.25				1
GLLO	DSS-14,43	8.0	4.0	1.00	0.25	1	1	1	
GNS	34B1	4.0	4.0	1.00	0.25		3		3
GNS	34B1	8.0	4.0	1.00	0.25		1	5	
GNS	DSS-24,54	4.0	4.0	1.00	0.25	3			
GNS Maneuver	34B1	8.0	4.0	1.00	0.25			6	
GSSR Mercury	DSS-14	5.5	5.5	1.50	0.50	2			
IMAG	34B1	0.8	0.8	1.00	0.25		13	13	13
IMAG	34B1	1.5	1.5	1.00	0.25		1	1	1
IMAG	DSS-24,54	0.8	0.8	1.00	0.25	13			
IMAG	DSS-24,54	1.5	1.5	1.00	0.25	1			
M01O DDOR	DSS-43,34	8.0	4.0	1.00	0.25		1		1
M010 DDOR	DSS-25	8.0	4.0	1.00	0.25		1		1
M01O Map/MGS Map	DSS-14,43,65	8.0	4.0	1.00	0.25	5			
M01O Map/MGS Map	DSS-14,43,45,65	7.0	4.0	1.00	0.25	5			
M01O Mapping	DSS-14,43,45,65	7.0	4.0	1.00	0.25	4			
M01O Mapping	DSS-25,34,54	7.0	7.0	1.00	0.25		12	14	12
MAP.	70M	0.7	0.6	1.25	0.25				4
MAP.	DSS-14,43	0.7	0.6	1.25	0.25	7	7	7	
MAP. Mnvr.	70M	5.0	5.0	1.25	0.25				1
MAP. Mnvr.	70M	3.0	3.0	1.25	0.25				2



		Duratio	ons	Calibra	tion		April		
User	Resource	Ave	Min	Pre	Post	14	15	16	17
MGS Map/Beta Sup	DSS-14,43	8.0	4.0	1.00	0.25		4	4	
MGS Map/Beta Sup	34H	12.0	4.0	1.00	0.25				10
MGS Map/Beta Sup	DSS-65	7.5	4.0	1.00	0.25		5	5	
ROSE Launch	DSS-54	8.0	4.0	1.00	0.25	7			
ROSE Nav Campaign	DSS-14,25,26	8.0	4.0	1.00	0.25		7	7	
ROSE Nav Campaign	DSS-43,34,45	5.0	5.0	1.00	0.25		2	2	
ROSE Nav Campaign	DSS-65,54	5.0	5.0	1.00	0.25		5	5	
SDU	DSS-45,65	6.0	4.0	1.00	0.25	1	1	1	1
SGP Crust Dyn B-M4	DSS-65	18.0	14.0	1.50	0.50	1			
SGP Crust Dyn W-M4	DSS-45	18.0	14.0	1.50	0.50		1	1	
SOHO	DSS-27	4.0	4.0	0.40	0.20				2
SOHO	26M	9.6	6.0	0.70	0.20	7			
SOHO	26M	1.6	1.6	0.70	0.20	14			
SOHO	DSS-16,27,66	1.6	1.6	0.70	0.20		14	14	6
SOHO	DSS-16,66	9.6	6.0	0.70	0.20		7	7	
SOHO	DSS-16,34,66	4.0	4.0	0.70	0.20				2
SOHO TSO	DSS-14	4.0	4.0	0.45	0.25				5
SOHO TSO	DSS-16	4.0	4.0	0.70	0.20				5
SOHO TSO	DSS-34,66	8.0	4.0	0.70	0.20				10
STF	DSS-45,65	1.0	1.0	0.75	0.25		4	7	7
STF	DSS-25,34,54	1.0	1.0	0.75	0.25		4	7	7
STF IOC	DSS-14,43,54	8.0	1.0	0.75	0.25	21	9		
ULYS	DSS-14	5.0	5.0	1.00	0.25	7	7	7	7
ULYS	DSS-24	5.0	5.0	1.00	0.25	7	7	7	7
VGR1	DSS-14,63	8.0	8.0	0.50	0.25				7
VGR1	DSS-26	8.0	8.0	0.50	0.25	7	7	7	7
VGR1 Routine U/L	70M	2.5	2.5	0.75	0.25				1
VGR1 Routine U/L	DSS-14,43	2.5	2.5	0.75	0.25	1	1	1	



		Duratio	ons	Calibra	ation		A	pril		
User	Resource	Ave	Min	Pre	Post	14	15	16	17	
WIND	DSS-24,54	5.0	4.5	1.00	0.25	3				
WIND	34B1	5.0	4.5	1.00	0.25		3		3	3



JURAP Resource Allocation Review Analysis and Recommendations

Analysis and Recommendations

2003 - May (Weeks 18 - 22)



DSS-14 Downtime (NSP) in Weeks 18-20

DSS-45 Downtime (NSP) in Week 18 Only

Proposal

DSS-46 Downtime (Servo Drive) in Weeks 18-20

DSS-54 Downtime (NSP) in Weeks 18-20 Proposal

Voyager 1 ASCAL support in Week 19 Voyager 1 DTR Array support in Week 18 Voyager 1 MAGROL support in Week 19 Cassini TCM support in Week 18 Cassini TCM Day support in Week 18

ANALYSIS

1. DSS-14 will be down for NSP re-plan from Week 17 (Monday DOY 111) through Week 20 (Monday DOY 132) affecting: Galileo, GBRA, GPB, GSSR, MAP, Maintenance, MEGA, Ulysses and VGR1


SDU MO1C,MGS
VGR2
VGR2
VGR1
SPTF
JUYS ROSE

May '03



JURAP Resource Allocation Review Analysis and Recommendations

2003 - May (Weeks 18 - 22)



May '03

ANALYSIS (continued)

- 2. DSS-45 will be down for NSP re-plan from Week 15 (Monday DOY 097) through Week 18 (Friday DOY 122) affecting: Cassini, Cluster, MGS Mapping, Stardust, STF
- 3. DSS-54 will be down for NSP re-plan from Week 17 (Monday DOY 111) through Week 20 (Monday DOY 132) affecting: CHDR, Genesis, Image, Maintenance, Mapping, M01O, Nozomi, Polar, STF, Ulysses, and Wind



RECOMMENDATIONS

DSS-14

- ◆ DSS Antenna Cals at 70M in Weeks 18 and 19 change to DSS-43, 63
- ◆ DSS Maintenance delete routine and bearing support in Weeks 18,19 and delete one routine maintenance in Week 20 (Monday)
- ◆ GBRA M-Wave Spect at 70M in Weeks 18 and 19 change to DSS-43, 63 and reduce to 2 supports per week
- **◆ GBRA delete Planet R/AST support in Weeks 18 and 19**
- ♦ GBRA VLBA SOC-M4 at DSS-14/63 in Week 19 move to Week 20
- ◆ Galileo routine support at 70M in Weeks 18 and 19 change to DSS-43, 63
- ◆ Gravity Probe B move DSS-14, 12-hour support; DSS-63, 8-hour support; and DSS-43, 6.5 hour support in Week 19 to Week 20*
- ◆ GSSR delete GODR support at DSS-14/15 in Week 19*
- ◆ MAP routine support at 70M Weeks 18 and 19 change to DSS-43, 63*
- **◆ MEGA routine support at 70M in Week 19 change to DSS-43, 63**
- Ulysses routine support at DSS-14 in Week 18 and 19 move to DSS-15 (D/L only)

JV rev.1 - 19

^{*} Recommendation accepted



RECOMMENDATIONS

DSS-14 (continued)

- ♦ Voyager 1 routine uplink support at 70M in Weeks 18 and 19 change to DSS-43, 63*
- ♦ Voyager 1 ASCAL support in Week 19 change to DSS-15*
- ♦ Voyager 1 delete DTR Array support at DSS-14/25, 14/26 in Week 18*
- ♦ Voyager 1 MAGROL support in Week 19 change to DSS-15*

DSS-45

- ◆ Cassini TCM support at DSS-45, 25 in Week 18 change to DSS-34, 25 *
- Cassini TCM Day support at DSS-45, 65, 25 in Week 18 change to DSS-34, 65, 25 *
- ◆ CLU2 SSO support at DSS-34/43/45 in Week 18 change to DSS-34/43*
- **◆ DSS Maintenance delete support in Week 18**
- ◆ MGS Map/Beta support at 34H in Week 18 change to DSS-15, 34, 65*
- ◆ Stardust routine support at DSS-45, 65 in Week 18 change to DSS-15, 65*
- ◆ STF routine support at DSS-45, 65 in Week 18 change to DSS-15, 65

^{*} Recommendations accepted



RECOMMENDATIONS

DSS-54

- CHDR routine support at 34B1 in Weeks 18 and 19 change to DSS-24, 34, 66
- ◆ DSS Maintenance delete support in Weeks 18 and 19
- ◆ Genesis routine support in Weeks 18 and 19 change to DSS-24, 34*
- ♦ IMAGE routine support at 34B1 in Weeks 18 and 19 change to DSS-24, 34*
- Nozomi routine support at DSS-24,54 in Weeks 18 and 19 change to DSS-24
- Mars Odyssey Mapping support at DSS-25, 34, 54 in Weeks 18 and 19 change to DSS-24, 34, 65*
- ◆ Polar PB support at 34B1 in Week 19 change to DSS-24, 66*
- Ulysses routine support at DSS-54 in Week 18 and 19 change to DSS-65 (D/L only)
- ♦ WIND routine support at 34B1 in Weeks 18 and 19 change to DSS-24, 34*
- **◆ STF routine support at DSS-25, 34, 54 in Weeks 18 and 19 change to DSS-25, 34, 63**

^{*} Recommendation accepted



CAS TCM DSS-45,25 9.0 4.0 1.00 0.25 3 4 2 CAS TCM Day DSS-45,65,25 8.0 4.0 1.00 0.25 3 CAS TCM Day DSS-45,65,25 8.0 4.0 1.00 0.25 3 CLUZ 1/2/3/4 SSO DSS-34/45/43 2.0 2.0 0.50 0.25 1 1 1 1 1 CLUZ 1/2/3/4 SSO DSS-16/27/24/15 2.0 1.0 0.50 0.25 2 2 2 2 2 2 2 CLUZ 1/2/3/4 SSO DSS-16/27/24/14 2.0 1.0 0.50 0.25 2 CLUZ 1/2/3/4 SSO DSS-16/27/24/14 2.0 1.0 0.50 0.25 1 CLUZ 1/2/3/4 SSO DSS-16/27/24/15 1.5 1.0 0.50 0.25 1 CLUZ 1/2/3/4 SSO DSS-34/43/45 2.0 1.0 0.50 0.25 1 CLUZ 1/2/3/4 SSO DSS-34/43/45 2.0 1.0 0.50 0.25 1 CLUZ 1/2/3/4 SSO DSS-34/43/45 2.0 1.0 0.50 0.25 1 CLUZ 1/2/3/4 SSO DSS-34/43/45 2.0 1.0 0.50 0.25 1 CLUZ 1/2/3/4 SSO DSS-34/43/45 2.0 1.0 0.50 0.25 1 CLUZ 1/2/3/4 SSO DSS-34/34/45 2.0 1.0 0.50 0.50 0.25 1 CLUZ 1/2/3/4 SSO DSS-34/34/45 2.0 1.0 0.50 0.50 0.25 1 CLUZ 1/2/3/4 SSO DSS-34/34/45 2.0 1.0 0.50 0.50 0.25 1 CLUZ 1/2/3/4 SSO DSS-34/34/45 2.0 1.0 0.50 0.50 1 CSSN Antenna Cal 70M 8.0 8.0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1											
CAS DSS-45,25 9.0 4.0 1.00 0.25 1 2 2 CAS TCM DSS-45,25 9.0 4.0 1.00 0.25 3 4 2 CAS TCM Day DSS-45,65,25 8.0 4.0 1.00 0.25 3 4 2 CHDR 34B1 1.0 1.0 1.00 0.25 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 21 22 2 2 2 2 2 2 2			Duratio	ons	Calibra	tion			May		
CAS TCM DSS-45,25 9.0 4.0 1.00 0.25 3 4 2 CAS TCM Day DSS-45,65,25 8.0 4.0 1.00 0.25 3 CAS TCM Day DSS-45,65,25 8.0 4.0 1.00 0.25 3 CLUZ 1/2/3/4 SSO DSS-34/45/43 2.0 2.0 0.50 0.25 1 1 1 1 1 CLUZ 1/2/3/4 SSO DSS-16/27/24/15 2.0 1.0 0.50 0.25 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	User	Resource	Ave	Min	Pre	Post	18	19	20	21	22
CAS TCM Day DSS-45,65,25 8.0 4.0 1.00 0.25 3 CHDR 34B1 1.0 1.0 1.0 1.00 0.25 21 21 21 21 21 21 21 2: CLU2 1/2/3/4 SSO DSS-34/45/43 2.0 2.0 0.50 0.25 1 1 1 1 1 1 CLU2 1/2/3/4 SSO DSS-16/27/24/14 2.0 1.0 0.50 0.25 2 CLU2 1/2/3/4 SSO DSS-16/27/24/14 2.0 1.0 0.50 0.25 2 CLU2 1/2/3/4 SSO DSS-16/27/24/14 2.0 1.0 0.50 0.25 2 CLU2 1/2/3/4 SSO DSS-34/34/5 2.0 1.0 0.50 0.25 2 CLU2 1/2/3/4 SSO DSS-34/34/5 2.0 1.0 0.50 0.25 1 CLU2 1/2/3/4 SSO DSS-34/34/5 2.0 1.0 0.50 0.25 1 CLU2 1/2/3/4 SSO DSS-34/34/5 2.0 1.0 0.50 0.25 1 CLU2 1/2/3/4 SSO DSS-34/34/5 2.0 1.0 0.50 0.25 1 CLU2 1/2/3/4 SSO DSS-34/34/5 2.0 1.0 0.50 0.25 1 CLU2 1/2/3/4 SSO DSS-34/34/5 2.0 1.0 0.50 0.25 1 CLU2 1/2/3/4 SSO DSS-34/34/5 2.0 1.0 0.50 0.25 1 CLU2 1/2/3/4 SSO DSS-34/34/5 2.0 1.0 0.50 0.25 1 CLU2 1/2/3/4 SSO DSS-34/34/5 2.0 1.0 0.50 0.25 1 CLU2 1/2/3/4 SSO DSS-34/34/5 2.0 1.0 0.50 0.25 1 CLU2 1/2/3/4 SSO DSS-34/34/5 2.0 1.0 0.50 0.25 1 CLU2 1/2/3/4 SSO DSS-34/34/5 2.0 1.0 0.50 0.25 1 CSS Naintenance I SS-16/6 2.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0	CAS	DSS-45,25	9.0	4.0	1.00	0.25			1	2	2
CHDR 34B1 1.0 1.0 1.00 0.25 21 21 21 21 21 21 22 CLU2 1/2/3/4 SSO DSS-34/45/43 2.0 2.0 0.50 0.25 1 1 1 1 1 1 1 CLU2 1/2/3/4 SSO DSS-16/27/24/15 2.0 1.0 0.50 0.25 2 2 2 2 2 2 2 CLU2 1/2/3/4 SSO DSS-16/27/24/14 2.0 1.0 0.50 0.25 2 2 2 2 2 2 CLU2 1/2/3/4 SSO DSS-16/27/24/14 2.0 1.0 0.50 0.25 2 CLU2 1/2/3/4 SSO DSS-16/27/24/15 1.5 1.0 0.50 0.25 1 CLU4 1/2/3/4 MSO DSS-34/43/45 2.0 1.0 0.50 0.25 1 CLU4 1/2/3/4 MSO 16/27/24/15 1.5 1.0 0.50 0.25 1 CLU4 1/2/3/4 MSO 16/27/24/15 1.5 1.0 0.50 0.25 1 CLU4 1/2/3/4 MSO 15/27/24/15 1.5 1.0 0.50 0.25 1 CLU4 1/2/3/4 MSO 16/27/24/15 1.5 1.0 0.50 0.25 1 CLU4 1/2/3/4 MSO 16/27/24/15 1.5 1.0 0.50 0.25 1 CLU4 1/2/3/4 MSO 16/27/24/15 1.5 1.0 0.50 0.25 1 CLU4 1/2/3/4 MSO 16/27/24/15 1.5 1.0 0.50 0.25 1 CLU4 1/2/3/4 MSO 16/27/24/15 1.5 1.0 0.50 0.25 1 CLU4 1/2/3/4 MSO 16/27/24/15 1.5 1.0 0.50 0.25 1 CLU4 1/2/3/4 MSO 16/27/24/15 1.5 1.0 0.50 0.25 1 CLU4 1/2/3/4 MSO 16/27/24/15 1.5 1.0 0.50 0.25 1 CLU4 1/2/3/4 MSO 16/27/24/15 1.5 1.0 0.50 0.25 1 CLU4 1/2/3/4 MSO 16/27/24/15 1.5 1.0 0.50 0.50 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	CAS TCM	DSS-45,25	9.0	4.0	1.00	0.25	3	4	2		
CLU2 1/2/3/4 SSO DSS-34/45/43 2.0 2.0 0.50 0.25 1 1 1 CLU2 1/2/3/4 SSO DSS-16/27/24/15 2.0 1.0 0.50 0.25 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	CAS TCM Day	DSS-45,65,25	8.0	4.0	1.00	0.25	3				
CLU2 1/2/3/4 SSO DSS-16/27/24/15 2.0 1.0 0.50 0.25 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	CHDR	34B1	1.0	1.0	1.00	0.25	21	21	21	21	21
CLU2 1/2/3/4 SSO DSS-16/27/24/14 2.0 1.0 0.50 0.25 2 CLU2 1/2/3/4 SSO DSS-34/43/45 2.0 1.0 0.50 0.25 1 CLU4 1/2/3/4 MSO 16/27/24/15 1.5 1.0 0.50 0.25 1 DSN Antenna Cal 70M 8.0 8.0 1 1 1 DSN Clock Syn D-M4 15/45,15/65 24.0 24.0 1.50 0.50 1 1 DSN Clock Syn D-M4 DSS-15/65 4.0 4.0 1.50 0.50 1 1 DSN Clock Syn D-M4 DSS-14 8.0 8.0 1 1 1 DSS Bearing Mntc DSS-43 8.0 8.0 1 1 1 DSS Bearing Mntc DSS-43 8.0 8.0 1 1 1 DSS Maintenance DSS-54 6.0 6.0 1 1 1 1 DSS Maintenance DSS-27 8.0 6.0 1 1 1	CLU2 1/2/3/4 SSO	DSS-34/45/43	2.0	2.0	0.50	0.25		1	1	1	1
CLU2 1/2/3/4 SSO DSS-34/43/45 2.0 1.0 0.50 0.25 1 CLU4 1/2/3/4 MSO 16/27/24/15 1.5 1.0 0.50 0.25 1 DSN Antenna Cal 70M 8.0 8.0 1 1 1 DSN CAT M&E D-M4 15/45,15/65 24.0 24.0 1.50 0.50 1 1 DSN Clock Syn D-M4 DSS-15/65 4.0 4.0 1.50 0.50 1 1 DSN Clock Syn D-M4 DSS-65 4.0 4.0 1.50 0.50 1 1 DSS Bearing Mntc DSS-14 8.0 8.0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 <td< td=""><td>CLU2 1/2/3/4 SSO</td><td>DSS-16/27/24/15</td><td>2.0</td><td>1.0</td><td>0.50</td><td>0.25</td><td></td><td>2</td><td>2</td><td>2</td><td>2</td></td<>	CLU2 1/2/3/4 SSO	DSS-16/27/24/15	2.0	1.0	0.50	0.25		2	2	2	2
CLU4 1/2/3/4 MSO 16/27/24/15 1.5 1.0 0.50 0.25 1 DSN Antenna Cal 70M 8.0 8.0 1 1 1 DSN CAT M&E D-M4 15/45,15/65 24.0 24.0 1.50 0.50 1 1 DSN Clock Syn D-M4 DSS-15/65 4.0 4.0 1.50 0.50 1 1 DSN Clock Syn D-M4 DSS-65 4.0 4.0 1.50 0.50 1 1 DSN Clock Syn D-M4 DSS-65 4.0 4.0 1.50 0.50 1 1 DSS Bearing Mntc DSS-65 4.0 4.0 1.50 0.50 1 1 DSS Bearing Mntc DSS-43 8.0 8.0 8.0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	CLU2 1/2/3/4 SSO	DSS-16/27/24/14	2.0	1.0	0.50	0.25	2				
DSN Antenna Cal 70M 8.0 8.0 1 1 1 DSN CAT M&E D-M4 15\4515\65 24.0 24.0 1.50 0.50 1 1 DSN Clock Syn D-M4 DSS-15\65 4.0 4.0 1.50 0.50 1 DSN Clock Syn D-M4 DSS-65 4.0 4.0 1.50 0.50 1 DSS Bearing Mntc DSS-14 8.0 8.0 1 1 1 DSS Bearing Mntc DSS-43 8.0 8.0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	CLU2 1/2/3/4 SSO	DSS-34/43/45	2.0	1.0	0.50	0.25	1				
DSN CAT M&E D-M4 1545,15665 24.0 24.0 1.50 0.50 1 1 DSN Clock Syn D-M4 DSS-15665 4.0 4.0 1.50 0.50 1 DSN Clock Syn D-M4 DSS-665 4.0 4.0 1.50 0.50 1 DSS Bearing Mntc DSS-14 8.0 8.0 1 1 DSS Bearing Mntc DSS-43 8.0 8.0 1 1 DSS Bearing Mntc DSS-63 8.0 8.0 1 1 DSS Maintenance DSS-63 8.0 8.0 1 1 DSS Maintenance DSS-54 6.0 6.0 1 1 1 1 DSS Maintenance DSS-25 8.0 6.0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	CLU4 1/2/3/4 MSO	16/27/24/15	1.5	1.0	0.50	0.25			1		
DSN Clock Syn D-M4 DSS-15/65 4.0 4.0 1.50 0.50 1 DSN Clock Syn D-M4 DSS-65 4.0 4.0 1.50 0.50 1 DSS Bearing Mntc DSS-14 8.0 8.0 1 1 DSS Bearing Mntc DSS-43 8.0 8.0 1 1 DSS Bearing Mntc DSS-63 8.0 8.0 1 1 DSS Maintenance DSS-63 8.0 8.0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 <td< td=""><td>DSN Antenna Cal</td><td>70M</td><td>8.0</td><td>8.0</td><td></td><td></td><td>1</td><td>1</td><td>1</td><td></td><td></td></td<>	DSN Antenna Cal	70M	8.0	8.0			1	1	1		
DSN Clock Syn D-M4 DSS-65 4.0 4.0 1.50 0.50 1 DSS Bearing Mntc DSS-14 8.0 8.0 1 1 DSS Bearing Mntc DSS-43 8.0 8.0 1 DSS Bearing Mntc DSS-63 8.0 8.0 1 DSS Maintenance DSS-54 6.0 6.0 1 1 1 1 DSS Maintenance DSS-25 8.0 6.0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	DSN CAT M&E D-M4	15\45,15\65	24.0	24.0	1.50	0.50		1	1		
DSS Bearing Mntc DSS-14 8.0 8.0 1 1 DSS Bearing Mntc DSS-43 8.0 8.0 1 DSS Bearing Mntc DSS-63 8.0 8.0 1 DSS Maintenance DSS-54 6.0 6.0 1 1 1 1 DSS Maintenance DSS-25 8.0 6.0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 <td>DSN Clock Syn D-M4</td> <td>DSS-15\65</td> <td>4.0</td> <td>4.0</td> <td>1.50</td> <td>0.50</td> <td></td> <td></td> <td>1</td> <td></td> <td>1</td>	DSN Clock Syn D-M4	DSS-15\65	4.0	4.0	1.50	0.50			1		1
DSS Bearing Mntc DSS-43 8.0 8.0 1 DSS Bearing Mntc DSS-63 8.0 8.0 1 DSS Maintenance DSS-54 6.0 6.0 1 1 1 1 DSS Maintenance DSS-55 8.0 6.0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	DSN Clock Syn D-M4	DSS-65	4.0	4.0	1.50	0.50	1				
DSS Bearing Mntc DSS-63 8.0 8.0 1 DSS Maintenance DSS-54 6.0 6.0 1 1 1 1 1 DSS Maintenance DSS-25 8.0 6.0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	DSS Bearing Mntc	DSS-14	8.0	8.0			1			1	
DSS Maintenance DSS-54 6.0 6.0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 <td>DSS Bearing Mntc</td> <td>DSS-43</td> <td>8.0</td> <td>8.0</td> <td></td> <td></td> <td></td> <td>1</td> <td></td> <td></td> <td>1</td>	DSS Bearing Mntc	DSS-43	8.0	8.0				1			1
DSS Maintenance DSS-25 8.0 6.0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 <td>DSS Bearing Mntc</td> <td>DSS-63</td> <td>8.0</td> <td>8.0</td> <td></td> <td></td> <td></td> <td></td> <td>1</td> <td></td> <td></td>	DSS Bearing Mntc	DSS-63	8.0	8.0					1		
DSS Maintenance DSS-27 8.0 6.0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 <td>DSS Maintenance</td> <td>DSS-54</td> <td>6.0</td> <td>6.0</td> <td></td> <td></td> <td>1</td> <td>1</td> <td>1</td> <td>1</td> <td>1</td>	DSS Maintenance	DSS-54	6.0	6.0			1	1	1	1	1
DSS Maintenance DSS-15 8.0 6.0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 <td>DSS Maintenance</td> <td>DSS-25</td> <td>8.0</td> <td>6.0</td> <td></td> <td></td> <td>1</td> <td>1</td> <td>1</td> <td>1</td> <td>1</td>	DSS Maintenance	DSS-25	8.0	6.0			1	1	1	1	1
DSS Maintenance DSS-45 6.0 6.0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 <td>DSS Maintenance</td> <td>DSS-27</td> <td>8.0</td> <td>6.0</td> <td></td> <td></td> <td>1</td> <td>1</td> <td>1</td> <td>1</td> <td>1</td>	DSS Maintenance	DSS-27	8.0	6.0			1	1	1	1	1
DSS Maintenance DSS-24 8.0 6.0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 <td>DSS Maintenance</td> <td>DSS-15</td> <td>8.0</td> <td>6.0</td> <td></td> <td></td> <td></td> <td>1</td> <td>1</td> <td>1</td> <td>1</td>	DSS Maintenance	DSS-15	8.0	6.0				1	1	1	1
DSS Maintenance DSS-65 6.0 6.0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 <td>DSS Maintenance</td> <td>DSS-45</td> <td>6.0</td> <td>6.0</td> <td></td> <td></td> <td>1</td> <td>1</td> <td>1</td> <td>1</td> <td>1</td>	DSS Maintenance	DSS-45	6.0	6.0			1	1	1	1	1
DSS Maintenance DSS-26 8.0 6.0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 <td>DSS Maintenance</td> <td>DSS-24</td> <td>8.0</td> <td>6.0</td> <td></td> <td></td> <td>1</td> <td>1</td> <td>1</td> <td>1</td> <td>1</td>	DSS Maintenance	DSS-24	8.0	6.0			1	1	1	1	1
DSS Maintenance DSS-46 6.0 6.0 1 1 1 1 DSS Maintenance DSS-66 8.0 6.0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	DSS Maintenance	DSS-65	6.0	6.0			1	1	1	1	1
DSS Maintenance DSS-66 8.0 6.0 1 1 1 1 1 1 DSS Maintenance DSS-43 8.0 8.0 1 1 1 1	DSS Maintenance	DSS-26	8.0	6.0			1	1	1	1	1
DSS Maintenance DSS-43 8.0 8.0 1 1 1 1	DSS Maintenance	DSS-46	6.0	6.0						1	1
	DSS Maintenance	DSS-66	8.0	6.0			1	1	1	1	1
DSS Maintenance DSS-16 8.0 6.0 1 1 1 1 1 1	DSS Maintenance	DSS-43	8.0	8.0			1		1	1	
	DSS Maintenance	DSS-16	8.0	6.0			1	1	1	1	1



		Duratio	ns	Calibra	tion			May		
User	Resource	Ave	Min	Pre	Post	18	19	20	21	22
DSS Maintenance	DSS-34	6.0	6.0			1	1	1	1	1
DSS Maintenance	DSS-63	10.5	8.0			1	1		1	1
DSS Maintenance	DSS-63	6.0	4.0			1	1	1	1	1
DSS Maintenance	DSS-14	8.0	8.0			2	2	2	2	2
GBRA Host Country	DSS-43	24.0	8.0	0.75	0.25					1
GBRA Host Country	DSS-45	12.0	12.0	0.75	0.25			1		
GBRA M-Wave Spect	70M	9.0	4.0	0.50	0.50	3	3	3	3	3
GBRA Planet R/Ast	DSS-14	9.0	4.0	0.75	0.50	1	1	1		1
GBRA Planet R/Ast	DSS-14	4.0	4.0	0.75	0.50				1	
GBRA RA360 H20 MSR	DSS-63	12.0	4.0	1.50	0.50	2	2			
GBRA VLBA SOC-M4	DSS-14\63	8.0	8.0	1.50	0.50		1			
GLLO	70M	8.0	4.0	1.00	0.25	1	1	1	1	1
GNS	34B1	4.0	4.0	1.00	0.25	3	3	3	3	3
GPB BR071n SOC-M4	DSS-14	12.0	12.0	1.50	0.50		1			
GPB BR071n SOC-M4	DSS-63	8.0	8.0	1.50	0.50		1			
GPB BR071n SOC-M4	DSS-43	6.5	6.5	1.50	0.50		1			
GSSR GODR	DSS-14/15	8.0	4.0	1.50	0.50		1			1
GSSR Mercury	DSS-14	5.5	5.5	1.50	0.50					1
IMAG	34B1	0.8	0.8	1.00	0.25	13	13	13	13	13
IMAG	34B1	1.5	1.5	1.00	0.25	1	1	1	1	1
INTG	DSS-16	5.3	0.5	0.70	0.20	7	7	7	7	7
M010 DDOR	DSS-43,63	8.0	4.0	1.00	0.25		1			
M010 DDOR	DSS-43,34	8.0	4.0	1.00	0.25				1	
M010 DDOR	DSS-25	9.0	4.0	1.00	0.25		1		1	
M01O Map/MGS Map	DSS-25,34,54	7.0	4.0	2.00	0.25					5
M01O Mapping	DSS-25,34,54	7.0	7.0	1.00	0.25	14	12	14	12	9
MAP.	70M	0.7	0.6	1.25	0.25	4	7	7	7	7
MEGA	70M	8.0	4.0	1.50	0.50		1	1	1	



		Durations		Calibration		May				
User	Resource	Ave	Min	Pre	Post	18	19	20	21	22
MGS Map/Beta Sup	34H	12.0	4.0	1.00	0.25	9	9	10	9	4
NOZO	DSS-24,54	8.0	2.0	0.75	0.25	2	3	3	3	3
POLR PB	26M	1.0	0.8	0.70	0.20				28	28
POLR PB	DSS-16,27,66	1.0	0.8	0.70	0.20	28	17	17		
POLR PB	34B1	1.0	0.8	0.70	0.20		11	11		
POLR RT	DSS-27,66	2.0	2.0	0.40	0.20		7	7		
POLR RT	26M	2.0	2.0	0.70	0.20				7	7
POLR RT	DSS-16,27,66	2.0	2.0	0.70	0.20	7	7			
SDU	34H	6.0	4.0	1.00	0.25		1	1	1	1
SDU	DSS-45,65	6.0	4.0	1.00	0.25	1				
STF	DSS-45,65	1.0	1.0	0.75	0.25	7				
STF	DSS-25,34,54	1.0	1.0	0.75	0.25	7	14	14	14	14
ULYS	DSS-63,54	10.0	8.0	1.00	0.25	1	1	1	1	1
ULYS	DSS-14,24	10.0	8.0	1.00	0.25	4	4	4	4	4
ULYS	DSS-43,34	4.0	4.0	1.00	0.25	2	2	2	2	
ULYS	DSS-54,65	6.0	4.0	0.75	0.25	2	2	2	2	2
VGR1	DSS-63	4.0	4.0	0.50	0.25					7
VGR1	DSS-26,63	8.0	8.0	0.50	0.25	14	14	14	14	
VGR1	DSS-26	8.0	8.0	0.50	0.25					7
VGR1 ASCAL	DSS-14	2.0	2.0	0.75	0.25		1			
VGR1 DTR Array	DSS-14/25,14/26	7.4	7.4	1.25	0.25	1				
VGR1 MAGROL	DSS-14	7.0	7.0	0.75	0.25		1			
VGR1 Routine U/L	70M	2.5	2.5	0.75	0.25	1	1	1	1	1
WIND	34B1	5.0	4.5	1.00	0.25				3	3
WIND	34B1	4.0	4.0	1.00	0.25	3	3	3		
WIND TCM	DSS-34	3.0	2.0	0.50	0.25			1		



JOINT USERS RESOURCE ALLOCATION PLANNING MEETING (JURAP)

Action Item Status From 21 August 2001 RARB

(Resource Allocation Review Board)

David G. Morris

April 19, 2002

<u> </u>	Year	Month(s)	System	Responsible	Due Date	Status
01	2004	January	MER	J. Erickson	6/1/2002	Open

ACTION: Provide Final Landing Site coordinates (SPK file) for both Rovers one year prior to launch. (Reference A.I. #7 of August 13, 2001 RARB)

<i>AI</i> #	Year	Month(s)	System	Responsible	Due Date	Status
02	2003	January-December	DSMS P & C	R. Miller	4/18/2002	Open

ACTION: Investigate and Negotiate the feasibility of alternate assets providing current DSN Catalog Maintenance and Enhancement (CAT M&E) radio sources.

<i>AI</i> #	Year	Month(s)	System	Responsible	Due Date	Status
03	2003	January-December	SGP	N. Lacey P. Wolken	4/18/2002	Closed

ACTION: As a result of recommending deletion of the entire 2003 request of Space Geodesy Program, provide a listing of opportunities to the project to assist in their re-planning a reduced (hours) experiment.

RESPONSE: (4/16/02) The deletion of the 34H Antenna Controller Replacement tasks in 2003 has created 24 hour support opportunities for SGP as follows:

DSS-15: Weeks 14, 15, 16, 17 and 18 (April 2 through May 6).

DSS-45: Weeks 37, 38, 39, 40, 41, 42 and 43 (September 10 through October 28).

DSS-65: Weeks 37, 38, 39, 40, 41, 42 and 43 (September 10 through October 28).

<u> </u>	Year	Month(s)	System	Responsible	Due Date	Status
04	2003	January	SIRTF	P. Beyer	4/1/2002	Closed

ACTION: Perform telecom analysis to determine the adequacy of DSS-63 supporting spacecraft on day of launch. The expressed concern is that the DSS-63 X-band transmitter may saturate the SIRTF receiver. (DSS-65 has Downtime; DSS-54 is supporting Cassini GWE.)

RESPONSE: (4/4/02) Using 200 watts from DSS 63, the P_{total} into the Observatory will be -78 to -80 dBM. This should pose no risk to the spacecraft. HOWEVER, if the trajectory is anything off nominal, it is not good engineering practice to do a search with the 70M beamwidth. The 34M antenna is much more desirable for contingency purposes and SIRTF should have priority use of DSS-54.

<i>AI</i> #	Year	Month(s)	System	Responsible	Due Date	Status
05	2003	January-April	DSN	M. Wert	4/1/2002	Closed

ACTION: Investigate the impact to operations from deleting or reducing the 70m Antenna Calibrations in this period.

RESPONSE: (4/10/02) Minimum support has been analyzed and is provided:

- 1. GDSCC -- DSS14 can support forecast load if two 4-hr calibration blocks per month are provided Jan-Apr '03;
- 2. CDSCC -- DSS43 can support at one 4-hr calibration block per month during Jan-Apr '03;
- 3. MDSCC -- DSS63 can support at one 4-hr calibration block per month during Jan-Apr '03.

<i>AI</i> #	Year	Month(s)	System	Responsible	Due Date	Status
06	2003	November	MER-A,Ody	ssey J. Erickson	5/1/2002	Open

ACTION: MER-A agreed to modify DSN requests for Odyssey and MGS to fulfill required support in weeks 46-47 of November 2003.

<u> </u>	Year	Month(s)	System	Responsible	Due Date	Status
07	2003-2004	December-February	Mars Program	C. Whetsel	5/1/2002	Open

ACTION: Mars Program will evaluate support problems during the mid-December 2003 through end of February 2004 timeframe. All NASA and non-NASA Mars missions requirements will be evaluated and coordinated in light of the NASA Mars mission priorities and provided in time to be addressed at the August 2002 RARB.

<i>AI</i> #	Year	Month(s)	System	Responsible	Due Date	Status
08	2004	January	Cassini	B. Mitchell	5/1/2002	Open

ACTION: Cassini, based upon the recommendations of taking daily 1-4 hour gaps during the Canberra/Madrid overlap in January 2004, will evaluate impact to GWE. In addition, evaluate sliding the entire 40 days for the GWE earlier by a few weeks.

RESPONSE: RAT report is analyzing an alternate experiment period.

<i>AI</i> #	Year	Month(s)	System	Responsible	Due Date	Status
09	2004	January	MER-B	J. Erickson	4/18/2002	Open

ACTION: Mars Exploration Rover Project will evaluate whether MER-B can reduce coverage during critical MER-A TCMs (4, 5 and 6) in order that the support is used for a MER-A required hot-backup 34m antenna.

<u> </u>	Year	Month(s)	System	Responsible	Due Date	Status
10	2004	January	DSN	C. Jacobs	4/18/2002	Open

ACTION: Provide analysis of impact (e.g., to MER-B landing accuracy) of moving DSN Clock Sync VLBI out to week 4.

<i>AI</i> #	Year	Month(s)	System	Responsible	Due Date	Status
11	2004	January	MER	J. Ludwinski	2/26/2002	Closed

ACTION: Provide MER Project Surface Operations Viewperiods for the four primary and two alternate landing sites to RAPSO (J. Kehrbaum).

RESPONSE: Complete set of viewperiods were provided 8 March 2002.

<i>AI</i> #	Year	Month(s)	System	Responsible	Due Date	Status
12	2003-2004	November-February	y DSMS P & C	R. Miller	5/1/2002	Open

ACTION: Identify Risk Posture for individual mission's key events to plan steps the DSN can do to mitigate foreseeable anomalies (e.g., s/c emergency, station outages, MCD3 contention, etc.).

InterPlanetary Network and Information Systems Directorate DEEP SPACE MISSION SYSTEMS (DSMS)





JOINT USERS RESOURCE ALLOCATION PLANNING COMMITTEE



Resource Analysis Team

April 18, 2002

Nap Lacey

For Kevin Kim

InterPlanetary Network and Information Systems Directorate DEEP SPACE MISSION SYSTEMS (DSMS)



RESOURCE NEGOTIATION STATUS

- 2002 WEEKS 23 28 (THRU 07/14/2002) WILL BE RELEASED TO THE DSN ON 04/02/2002
- 2002 WEEK 29 32 (THRU 08/11/2002) WILL BE RELEASED ON 05/10/2002
- 2002 WEEKS 47 50 (THRU 12/15/2002) WILL GO INTO **NEGOTIATIONS STARTING 05/25/2002**

InterPlanetary Network and Information Systems Directorate DEEP SPACE MISSION SYSTEMS (DSMS)





◆ SPECIAL STUDIES/ACTIVITIES

- LUNAR-A LOAD STUDY
- MESSENGER LOAD STUDY
- CASSINI GWE
- GENESIS
- TDRS-J

♦ ON-GOING ACTIVITIES

- MADB/TIGRAS TESTING AND TRAINING
- DOWNTIME REPLANNING
- MID-RANGE SCHEDULE DEVELOPMENT

InterPlanetary Network and Information Systems Directorate



HTTP://RAPWEB.JPL.NASA.GOV


Major DSN Antenna Downtime Status

Jose Valencia April 18, 2002

MAJOR DSN DOWNTIMES by YEAR									
Year	Site	Description	Start	End	Duration (Days)	Weeks	Start DOY	End DOY	
2002	DSS 14	70M Servo Drive Replacement	07/15/02	09/27/02	75	29-39	196	270	
		Servo Drive Retrofit		09/17/02	15	36-38	246	260	
2002	DSS 24	NSP Implementation	10/21/02	12/12/02	53	43-50	294	346	
2002	DSS 24	4 NIB - 20 KW X-Band TXR Installation 10/21/02 12/12/02 53 43-50 294							
2002	DSS 43	70M Servo Drive Replacement	11/25/02	02/09/03	77	48-06	329	040	
2002	DSS 43	NIB - Ball-Joint Pad Refurbishment	11/25/02	02/09/03	77	48-06	329	040	
		NIB - NSP Implementation		02/09/03		49-06	336	040	
2002	DSS 43	Hydrostatic Bearing Regrout	11/17/02	11/24/02		46-47	321	328	
2002	DSS 45	DSS 45 HVAC Upgrade	10/01/02	10/08/02	8	40-41	274	281	
2002	DSS 54	NIB - KA Band Encoder Mech Mod Kit Installation	10/01/02	10/20/02	20	40-42	274	293	
2002	DSS 54	NIB - Azimuth Axle Replacement		10/20/02	20	40-42	274	293	
2002	DSS 65	NSP Implementation	12/02/02	02/09/03	70	49-06	336	040	
2003	DSS 15	NIB - NSP Implementation	04/01/03	05/01/03	31	14-18	091	121	
		NSP Implementation		04/06/03	56	07-14	041	096	
2003								096	
2003								096	
2003	03 DSS 34 NSP Implementation 02/10/03 04/06/03 56 07-14							096	
2003	DSS 34	NIB - 20 KW X-Band TXR Installation	02/10/03	04/06/03	56	07-14	041	096	
2003	DSS 34	NIB - KA-Band Encoder Mech Mod-Kit Installation	02/10/03	03/02/03	21	07-09	041	061	
		NIB - Azimuth Axle Replacement		03/02/03	21	07-09	041	061	
		Servo Drive Replacement	04/07/03	05/18/03	42	15-20	097	138	
		20 KW X-Band TXR Installation		08/31/03	42	30-35	202	243	
	03 DSS 63 70M Servo Drive Replacement 02/10/03 04/20/03 70 07-16 041 110								
								110	
2003	DSS 63	NIB - NSP Implementation	02/10/03	04/06/03	56	07-14	041	096	
2004	DSS 14	Antenna Controller Replacement	07/05/04	10/03/04	91	28-40	187	277	
		Antenna Controller Replacement		06/27/04	49	20-26	131	179	

Major Antenna Downtimes as Posted http://rapweb.jpl.nasa.gov

2002



2004

910 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52

D34 Azimuth Axle Replace (NIB)

January	February	March	April	May	June	July	August	September	October	November	December
1 2 3 4 5 6	6 7 8 9	10 11 12 13	14 15 16 17 18	19 20 21 22	23 24 25 26	27 28 29 30 31	32 33 34 35	36 37 38 39 40	41 42 43 44	45 46 47 48 49	50 51 52 53
				D65 A	ntenna Contro	oller					
							D14 Antenna	Controller			
									-		
1 2 3 4 5 6	6 7 8 9	10 11 12 13	14 15 16 17 18	3 19 20 21 22	23 24 25 26	27 28 29 30 31	32 33 34 35	36 37 38 39 40	41 42 43 44	45 46 47 48 49	9 50 51 52 53

4/24/2002


CHANGES TO ANTENNA DOWNTIME SCHEDULE SINCE MARCH 21 JURAP

- DSS-14 NSP in 2002 is deleted and proposal for DSS-14 NSP implementation in 2003 is being worked
- DSS-45 NSP in 2002 is deleted and proposal for DSS-43 NSP implementation in 2003 is being worked
- DSS-54 NSP in 2002 is deleted and proposal for DSS-54 NSP implementation in 2003 is being worked
- DSS-54 KA-band Encoder in 2002 is deleted and proposal for implementation in 2003 is being worked
- DSS-15 Antenna Controller Replacement (ACR) in 2003 is deleted and proposal for DSS-15 ACR implementation in 2004 is being worked
- Added DSS-43 Antenna downtime for re-grout work in 2002
- Added DSS-45 downtime for HVAC (Heating Ventilation and Air Conditioning) upgrade

4/24/2002


Task Schedule for 2002

- DSS-16 Servo Drive Retrofit
- 2. DSS-14 Servo Drive upgrade
- 3. DSS-24 NSP
 - X-Band 20Kw (NIB)
 - KA-Band Encoder (NIB)
- 4. DSS-54 Azimuth Axle replacement
- 5. DSS-43 Ball-joint Pad Refurbishment / re-grout
- 6. DSS-43 Servo Drive
- 7. DSS-45 HVAC



4/24/2002


Goldstone Solar System Radar



Martin A. Slade
April 18, 2002

NASA Jet Propulsion Laboratory

Joint Users Resource Allocation Planning Committee Meeting



Goldstone Solar System Radar (GSSR)

- On March 12, 2002 and March 16, 2002, the Goldstone Solar System Radar carried out successful observations of near-Earth Asteroid 2000 GD2.
- On April 2, April 3, and April 4, 2002, GSSR radar observations were successfully performed on near-Earth Asteroid 2002 FD6. Thanks to VGR1, Ulysses, and GBRA for giving up time for this short-notice event!
- The first NEA to have a significant chance (1/300) of hitting the Earth was described in the journal SCIENCE on April 5, 2002. The JPL press release can be found at: http://www.jpl.nasa.gov/releases/2002/release_2002_79.html with images at: http://neo.jpl.nasa.gov
- In another article in SCIENCE appearing April 12, 2002, the implications of ~16% of the near-Earth asteroid population being binary systems was discussed. The JPL press release can be found at:

 http://www.ipl.nasa.gov/rologsas/2002/rologsa_2002_83_html

http://www.jpl.nasa.gov/releases/2002/release_2002_83.html
Images and animations can be reached through: http://reason.jpl.nasa.gov



Joint Users Resource Allocation Planning Committee



RADIO ASTRONOMY AND SPECIAL ACTIVITIES

George Martinez April 18, 2001



TEMPO

(Time and Earth Motion Precision Observations

- Clock Sync
 - DOY 067
 - No problems were reported by either DSS-15 or DSS-65.
 - Data tapes sent to the JPL Correlator for processing.
 - DOY 081
 - No problems were reported by either DSS-15 or DSS-65.
 - Data tapes sent to the JPL Correlator for processing.
- Metrics
 - 2 observations 100% of data time utilized.




Cat M&E

- DOY 076
 - No problems were reported by DSS-15.
 - DSS-45 reported recorder problems.
 - Data tapes sent to the JPL Correlator for processing.
- DOY 083
 - No problems were reported by DSS-15.
 - DSS-65 reported recorder problems.
 - Data tapes sent to the JPL Correlator for processing.
- Metrics
 - 98% of data time utilized.



Space Geodesy Program (SGP)

- Europe-63
 - The Europe experiments are to determine station coordinates and their evolution in the European geodetic VLBI network with the highest precision possible.
 - EAC problems encountered.
 - Data tapes sent to Bonn Correlator.
- Metrics
 - 94% of data time utilized.



VOYAGER


FLIGHT OPERATIONS


JOINT USERS RESOURCE ALLOCATION PLANNING COMMITTEE

J. C. Hall, Jr. April 18, 2002 NASA Jet Propulsion Laboratory



http://voyager.jpl.nasa.gov





VOYAGER

FLIGHT OPERATIONS



FLIGHT SYSTEM STATUS


MISSION STATUS

VOYAGER 1

- * HELIOCENTRIC DISTANCE 84.4 AU, RTLT 23h14m36s
- SPACECRAFT REMAINS HEALTHY
- MAJOR ACTIVITY: MAGROL, HYBIC SWAP, & ASCALS

VOYAGER 2

- * HELIOCENTRIC DISTANCE 66.8 AU, RTLT 18h30m16s
- SPACECRAFT REMAINS HEALTHY
- MAJOR ACTIVITY: PLAYBACK AND MAGROL



VOYAGER

FLIGHT OPERATIONS



GROUND SYSTEM STATUS

(March 16, 2002 – April 12, 2002)

DSN - OVERALL SUPPORT – GOOD


• High power transmitter supported in place of low power transmitter on DOY 086, 087, 091, & 101. Required disabling CPA alarms due to manual configuration of high power transmitter. Low power transmitter could only obtain 11.5 kW when 18 kW is required.

TOTAL SUPPORT TIME, OUTAGE TIME, % of OUTAGE TIME

S/C	SCHED SUPPORT	ACTUAL SUPPORT	70M TIME	SIGNIFICANT OUTAGE TIME	% of OUTAGE TIME
31	420.3	433.9*	153.3	7.9 (2.3)	2.4
32	283.6	283.6	100.6	0.0 (1.3)	0.5

*Thanks to all of the Projects for DSN support during the Voyager 1 HYBIC Swap

VOYAGER HOMEPAGE - http://voyager.jpl.nasa.gov





http://saturn.jpl.nasa.gov/cassini/index.shtml

Joint Users Resource Allocation Planning (JURAP) Committee Meeting

Dave Doody April 18, 2002

NASA / Jet Propulsion Laboratory



In Quiet Cruise Subphase through 8 July 2002

- S/C remains HGA-to-Earth except for specific short activities
- Next subphases are Space Science, Approach Science...

Operations are Basically Nominal

- Tour Science Planning continues
- Main Engine TCM-18 executed nominally DOY 093 during "NOPESWAP"
 - The TCM demonstrated use of automation being developed for Tour OTMs
- Minor S/C instrument anomalies being worked and recovered near real time
 - Further ISS decontamination in progress thru DOY 122.
- DSN support
 - CSOC "NOPESWAP" was ill-coordinated, and occurred at a bad time near TCM.
 - NOP <u>still</u> (<u>still</u>) being revised!
 - Routine tracking ops are going very well.
 - Minor anomalies being worked in real time, minimal data loss
 - RNG problem continues under investigation
 - Supporting NSP Doppler, RNG demos
 - Demonstrated NSP CMD with AMMOS v26.4/UPL D2 with two DSCCs
 - Hoping to report to next JURAP that NSP CMD is Cassini's operational system
 - Next milestone is determining whether to U/L CMD Sequence C32 on NSP CMD
 - GDSCC Array capability demo scheduled for DOY 121

Next Prime Mission Science

- Superior Conjunction RS experiment 2002 DOY 157 through 187
 - Met with NOPE, RS, Telecom and identified likely cause of missed U/L XFRs in GWE-1
- GWE#2 2002 DOY 341 through 2003 DOY 016



Mars Global Surveyor Flight Operations Status

E.E. Brower

April 18, 2002 JURAP

Mars Global Surveyor AGENDA

- Program / Project Status
- Recent Events/Accomplishments
- Mission Assessment
- Issues

MGS

Mars Global Surveyor

Program / Project Status

Detailed Description: (for items identified as yellow or red)


Technical:


Schedule:


Resources:

Programmatic:

NOTE: This is a rolling 4-month picture







Mars Global Surveyor Events

• Last 3 Months:

_	High Rate bias test	DEC 10
_	Odyssey A/B support end	JAN 10
_	MPL imaging	JAN 11-12
_	Resumed ROTOs	JAN 21
_	Completed 1 year of Extended Mission	JAN 31
_	Resumed 10h/d DSN tracking	FEB 1
_	Provided 3 gyro scale factor updates	FEB 20-27
_	Entered Contingency Mode	FEB 27
_	Resumed full instrument operation	MAR 11
_	Transitioned to Beta Supplement	MAR 13
_	Changed to lowest data rate	MAR 20
_	Entered Contingency Mode	APR 1
_	Resumed full instrument operation	APR 11

Mars Global Surveyor Recent Accomplishments

- P 20 Roll Only Targeted Observations (ROTO) were performed successfully bringing the total to 233 since the onset of the extended mission.
- P Preparations for the Beta Supplement transition were completed (table top Feb. 20) with March 13 commencement in the new spacecraft Relay-16 attitude. One week of medium telemetry rate occurred in the Beta mode and ROTOs were suspended in the first week.
- P A special non-comm. ROTO was performed on March 10 to demonstrate this capability for Beta Supplement operation.
- N The Thermal Emission Spectrometer (TES) performed two power restarts to clear sequencing problems introduced by activation of the image motion compensation software intended to provide the highest resolution thermal inertia measurements of MER landing sites.
- P Two prior gyro scale factor updates were uplinked with substantial improvement in STAREX convergence following ROTOs (<30 minutes).
- P Power management required adjustment of the Solar Array offset pointing from 25 to 0 deg.

Codes: P Per Plan

F Per Plan, but not previously forecasted in this report

N Not previously planned

L1,2,3 Late -- 1st, 2nd, 3rd time slipped

C Canceled -- not needed

MGS

Mars Global Surveyor Upcoming Events

- N Flight Rule: Stars near uncataloged objects will be removed from weekly swath catalog (not to be used for STAREX convergence).
- P Complete Mars Beta Supplement transition with non-comm. ROTOs
- P Prepare risk assessment update for E2 mission
- P Release Mission and Task Plan updates for E2 mission
- P End of Extended Mission #1, Begin Extended Mission #2 (E2)

Codes: P Per Plan

F Per Plan, but not previously forecasted in this report

N Not previously planned

L1,2,3 Late -- 1st, 2nd, 3rd time slipped

C Canceled -- not needed

Mars Global Surveyor Mission Assessment


- Spacecraft is in good health.
- UHF tests on June25-28 to confirmed relay health.
- Expect to fulfill most extended mission objectives (complete MER site coverage may become E2 mission objective).
- Expect to satisfy MER EDL Requirements.
- Chances of operation through 2004 are good.

Mars Global Surveyor Comments

- Radiated FSW patch to correct "feature" in FSW. This software patch will prevent loading the nadir quaternion upon SIS (Starex) reset.
 - When a SIS reset was performed prior to the patch a nadir quaternion (coordinates) reload of the AACS taking spacecraft attitude more than 5 degrees off sun (16 degrees) when in the Relay 16 mode.
 Consequently, the sun monitor tripped C-mode entry.

MGS





ULYSSES

JOINT USERS RESOURCE ALLOCATION PLANNING COMMITTEE

- SPACECRAFT OPERATIONS ARE NOMINAL. THE SPACECRAFT IS IN CONTINUOUS VIEW FROM THE NORTHERN HEMISPHERE AND OUT OF VIEW FROM THE SOUTHERN HEMISHERE.
- SPACECRAFT RECONFIGURATIONS AND INSTRUMENT CALIBRATIONS ARE PERFORMED AS REQUIRED.
- SPACECRAFT EARTH POINTING MANEUVERS ARE BEING PERFORMED EVERY 4 DAYS.



ULYSSES

JOINT USERS RESOURCE ALLOCATION PLANNING COMMITTEE

- SIGNIFICANT DISCREPANCY REPORTS FOR THIS JURAP PERIOD ARE LISTED BELOW:
 - 055/13:00 -> 13:20, DSS-54, DR:M100577; CPA4 failed during command transmission with 'COMMAND REGISTER SHIFT ERROR.' CPA4 was rebooted and re-validated, and the CMA was reset to make good. Command activity was nominal following recovery.
 - 057/11:45 -> 13:12, DSS-24, DR:G100855; With antenna on point and following spacecraft track the station was unable to configure the Block V Receiver. This was due to previous failure and troubleshooting was in progress. Several reboots of the complete BVR system were performed to no avail. Problem was eventually isolated to RMT1. Reconfiguration of the RTM systems were done so as to temporarily correct the problem and allow BVR configuration to proceed. While the BVR was inoperable commanding to the spacecraft was successfully performed in the 'blind pointing' mode of block command loads. It was decided not to send the daily, immediately executable, Stone command.
 - 057/15:00 -> 15:17, DSS-54, DR:M100581; Late AOS due to Antenna Elevation
 Angle Motor #1 controller failure. Defective controller was replaced to make good.
 17 minutes of realtime and 34 minutes of playback telemetry were lost. (51 minute total loss).



JOINT USERS RESOURCE ALLOCATION PLANNING COMMUTTEE



Brad Compton April 13, 2001



In Jet Propulation Laboratory

http://galileo.jpl.nasa.gov/



GALILEO MILLENIUM MISSION

ROUTINE ACTIVITIES

- Propulsion maintenance
- DMS conditioning
- Gyro performance test
- Science instrument MROs
- Attitude maintenance turn



GALILEO MILLENIUM MISSION

SIGNIFICANT EVENTS

- Completed final SSI and NIMS calibrations
- Completed I-33 playback (ends remote sensing for the Project)
- Magnetometer, Dust Detector and Extreme Ultraviolet data are being collected during the cruise part of this orbit
- Galileo team received a Space Foundation, 2002 Space Achievement Award at the 18th National Space Symposium
- During a routine DMS conditioning, the tape stopped and DMS fault protection was tripped
 - Real-time commands were sent to unlock and move the tape. The tape did move, but did not get into sync and high motor current values were seen. The problem continues to be investigated.




GALILEO MILLENIUM MISSION

PROJECT PLANS

- * Resolve DMS anomaly
- * Continue collecting MAG, DDS and EUV data
- * Continue routine activities
- * Next encounter, Amalthea 34 on 5 November





JOINT USERS
RESOURCE ALLOCATION
PLANNING COMMITTEE

R. E. Ryan April 18, 2002

NASA Jet Propulsion Laboratory

http://stardust.jpl.nasa.gov



Report to JURAP

STATUS

SPACECRAFT IS HEALTHY (4/18/02)
PRESENTLY 2.80 AU from EARTH

00:46:30 RTLT

2.72 AU from SUN

SPACECRAFT IS IN CRUISE

- BIT RATE IS AT 252 bps (on HGA/34 HEF)
- EARTH RANGE IS DECREASING, WILL GO TO 504 bps NEXT WEEK
- WE ARE TODAY, FARTHER FROM THE SUN THAN ANY U.S. SOLAR POWERED SPACECRAFT, AT APHELION OF 2.72 AU (Apr 17-18).
 - THE SOLAR PANELS, BATTERY AND POWER SYSTEM ARE PERFORMING VERY WELL











Report to JURAP

- CURRENT ACTIVITIES
 - MONITORING THE SPACECRAFT POWER SYSTEM NEAR MAX SOLAR RANGE FOR THIS AND THE NEXT APHELION
 - TWO HOUR COMM PERIODS ARE WORKING WELL
 - 2 HOURS, PLUS RTLT, FOR RANGING AND 2-WAY DOPPLER
 - PLANNING AND TESTING FOR ENCOUNTER
 - UPGRADE OF SPACECRAFT TEST LAB IS PROCEEDING
 - FSW UPGRADE OF THE NAV CAM NUCLEUS TRACKING S/W
- IPN SUPPORT HAS BEEN GOOD THIS PAST PERIOD











Report to JURAP

http://stardust.jpl.nasa.gov

UPCOMING EVENTS

INTERSTELLAR DUST COLLECTION 2
SECOND AEROGEL DEPLOY
JULY 27 TO DECEMBER 9, 2002

TCM 7a - SEPTEMBER 18, 2002

ASTERIOD ANNEFRANK FLYBY NOVEMBER 2, 2002









Report to JURAP

